

SAFETY INSPECTION REPORT

CONDUCTED FOR:
D.R. Horton, Inc. - Reno

PROJECT:
Sunrise - The Retreat



INSPECTION TYPE:
General Construction

INSPECTOR : SHAWN ST. PETERS
DATE : SEPTEMBER 06, 2024
CITY : RENO
STATE : NEVADA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53 Items Inspected	36 Satisfactory	0 Unsatisfactory	17 N/A
------------------------------	---------------------------	----------------------------	------------------

Sunrise Project has two recently painted duplexes. We have one new construction and another recently stuccoed on solitude scaffolding looks good and being inspected daily. Job site is very clean and well maintained. Three workers on site from Five Star Stucco. Housekeeping on the worksite is very good.

INSPECTION ITEMS

Documentation	
Site Contact	Satisfactory
Safety Program (Including IIPP)	Satisfactory
Heat Illness Prevention Program	Satisfactory
Comment	
Workers have adequate water and shade in the garages for workers to take their breaks.	-
Safety Data Sheets	Satisfactory
Daily Inspections	Satisfactory
Tailgate Meetings	Satisfactory
Sub-Contractor Meetings	Satisfactory
OSHA Permits	Satisfactory
Labor Law Postings	Satisfactory
Emergency / Other Postings	Satisfactory

First Aid / CPR Certification	Satisfactory
--------------------------------------	---------------------

Emergency Items

Access / Egress	Satisfactory
------------------------	---------------------

Elevator for Hoisting Workers (if needed)	N/A
--	------------

Fire Extinguisher(s)	Satisfactory
-----------------------------	---------------------

Comment	
Fire Extinguishers were inspected and in good condition.	-

First Aid Kit(s)	Satisfactory
-------------------------	---------------------

Comment	
First Aid Kits were available	-

Eye Wash Station	Satisfactory
-------------------------	---------------------

Other Fire Fighting Equipment (If needed)	N/A
--	------------

General Items

Restrooms	Satisfactory
------------------	---------------------

Comment	
Workers have adequate portable potties available when needed.	-

Hand Washing Stations	Satisfactory
------------------------------	---------------------

Waste Containers	Satisfactory
-------------------------	---------------------

Potable Water	Satisfactory
----------------------	---------------------

Shade	Satisfactory
--------------	---------------------

Comment	
----------------	--

Garage areas being utilized for shade for the workers.	-
--	---

Tools & Equipment

Power Tools	Satisfactory
Comment	
Safety glasses were being worn by the workers when visiting the worksite.	-

Hand Tools	Satisfactory
-------------------	---------------------

Powder Actuated Tools	Satisfactory
------------------------------	---------------------

Pneumatic Nailers	Satisfactory
--------------------------	---------------------

Mobile Elevated Work Platforms (MEWP's)	N/A
--	------------

Powered Industrial Trucks	N/A
----------------------------------	------------

Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
--	------------

Cranes	N/A
---------------	------------

Cylinder Storage	N/A
-------------------------	------------

Ladders	Satisfactory
Comment	
Extension ladders were tied off.	-

Operations

Personal Protective Equipment	Satisfactory
Comment	
Safety glasses were being worn by the workers when visiting the worksite.	-

Trenching & Excavation	N/A
Fall Protection	Satisfactory
Guardrails	Satisfactory
Floor / Wall Openings	Satisfactory
Supported Scaffolding	N/A
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Traffic Control	Satisfactory
Roofing Operations	Satisfactory
Housekeeping	Satisfactory
Demolition	N/A
Silica Control	Satisfactory
Comment	
Water truck onsite for silica dust control.	-
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	Satisfactory

Lockout / Tagout	N/A
-------------------------	------------

Stairways, Ramps, Runways	Satisfactory
----------------------------------	---------------------

Other Items (that were observed)	N/A
---	------------