

SAFETY INSPECTION REPORT

CONDUCTED FOR:
DR Horton

PROJECT:
Gosford East



INSPECTION TYPE:
General Construction

INSPECTOR : FRANCISCO ROMERO
DATE : JUNE 26, 2024
CITY : BAKERSFIELD
STATE : CALIFORNIA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53
Items Inspected

41
Satisfactory

0
Unsatisfactory

12
N/A

At my arrival, I saw Manuel on site, he was dealing with subs and he allowed me to do inspection.

Subs on site
Frontier Plumbing
East of Bay Plaster
Margarito Cabinets
AVINA Electric

During the inspection, there were a few subs working, a couple of subs were taking lunch, but I found no violations on site.

I will forward report for their review.

INSPECTION ITEMS

Documentation

Site Contact

Satisfactory

Safety Program (Including IIPP)

Satisfactory

Heat Illness Prevention Program

Satisfactory

Safety Data Sheets

Satisfactory

Daily Inspections

Satisfactory

Tailgate Meetings

Satisfactory

Sub-Contractor Meetings

Satisfactory

OSHA Permits**Satisfactory****Labor Law Postings****Satisfactory****Emergency / Other Postings****Satisfactory****First Aid / CPR Certification****Satisfactory****Emergency Items****Access / Egress****Satisfactory****Elevator for Hoisting Workers (if needed)****N/A****Fire Extinguisher(s)****Satisfactory****First Aid Kit(s)****Satisfactory****Eye Wash Station****Satisfactory****Other Fire Fighting Equipment (If needed)****Satisfactory****General Items****Restrooms****Satisfactory****Hand Washing Stations****Satisfactory****Waste Containers****Satisfactory****Potable Water****Satisfactory****Shade****Satisfactory****Tools & Equipment**

Power Tools	Satisfactory
Hand Tools	Satisfactory
Powder Actuated Tools	Satisfactory
Pneumatic Nailers	Satisfactory
Mobile Elevated Work Platforms (MEWP's)	N/A
Powered Industrial Trucks	N/A
Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Cranes	Satisfactory
Cylinder Storage	N/A
Ladders	Satisfactory
Operations	
Personal Protective Equipment	Satisfactory
Trenching & Excavation	Satisfactory
Fall Protection	Satisfactory
Guardrails	Satisfactory
Floor / Wall Openings	Satisfactory
Supported Scaffolding	Satisfactory
Mobile Scaffolding	N/A

Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Traffic Control	Satisfactory
Roofing Operations	Satisfactory
Housekeeping	Satisfactory
Demolition	N/A
Silica Control	Satisfactory
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	Satisfactory
Lockout / Tagout	Satisfactory
Stairways, Ramps, Runways	Satisfactory
Other Items (that were observed)	N/A