

SAFETY INSPECTION REPORT

CONDUCTED FOR:
Ed Grush General Contractor, Inc.

PROJECT:
Plaza Del Amo



INSPECTION TYPE:
General Construction

INSPECTOR: JASON CHAVEZ
DATE: JANUARY 27, 2025
CITY: TORRANCE
STATE: CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53
Items Inspected

21
Satisfactory

2
Unsatisfactory

30
N/A

The site was visited for a safety inspection. The contractors on site were observed regarding items including PPE, tools, and equipment and safe practices. Items of concern are noted in this report. The observations were discussed with the superintendent.

Contractors Onsite:
PJ Empire

Site Specific Activity:
Framing activities.

INSPECTION ITEMS

Documentation

Site Contact

Satisfactory

Comment

The superintendent Joe Mejia was onsite.

-

Safety Program (Including IIPP)

Satisfactory

Comment

Safety plan and IIPP is onsite and available.

-

Heat Illness Prevention Program

Satisfactory

Comment

This is located in the IIPP.

-

Safety Data Sheets

Satisfactory

Daily Inspections

Satisfactory

Tailgate Meetings**Satisfactory****Sub-Contractor Meetings****N/A****OSHA Permits****N/A****Labor Law Postings****Satisfactory****Comment**

Labor law is posted.

-

Emergency / Other Postings**Satisfactory****Comment**

Emergency contacts and postings are available.

-

First Aid / CPR Certification**Satisfactory****Emergency Items****Access / Egress****Satisfactory****Elevator for Hoisting Workers (if needed)****N/A****Fire Extinguisher(s)****Satisfactory****First Aid Kit(s)****Satisfactory****Comment**

The first aid kit is onsite and available.

-

Eye Wash Station**N/A****Other Fire Fighting Equipment (If needed)****N/A****General Items****Restrooms****Satisfactory**

Comment

Restrooms are onsite and available.

-

Hand Washing Stations

Satisfactory

Waste Containers

Satisfactory

Potable Water

N/A

Shade

N/A

Tools & Equipment

Power Tools

Unsatisfactory

Comment

PJ Empire

Workers have pinned back two power saws. This is prohibited. All guards must be in place at all times. The workers removed the pin and reported to the superintendent.



Hand Tools

Satisfactory

Powder Actuated Tools

N/A

Pneumatic Nailers

Satisfactory

Mobile Elevated Work Platforms (MEWP's)

N/A

Powered Industrial Trucks

N/A

Heavy Mobile Equipment (Excavators, Loaders, etc)

N/A

Cranes	N/A
---------------	------------

Cylinder Storage	N/A
-------------------------	------------

Ladders	N/A
----------------	------------

Operations

Personal Protective Equipment	Unsatisfactory
--------------------------------------	-----------------------

Comment	PJ Empire
<p>Workers are observed without hard hats. Please ensure all workers have required PPE. In addition, the workers have a scaffold that is placed on an extension ladder. This is prohibited and a manufactured scaffold system should be used to gain the required elevation.</p>	

Trenching & Excavation	Satisfactory
-----------------------------------	---------------------

Comment	Ed Grush
<p>Trenches and excavations are well delineated.</p>	

Fall Protection	Satisfactory
Guardrails	N/A
Floor / Wall Openings	N/A
Supported Scaffolding	N/A
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	N/A
Traffic Control	N/A
Roofing Operations	N/A
Housekeeping	Satisfactory
Demolition	N/A
Silica Control	N/A
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	Satisfactory
Lockout / Tagout	N/A
Stairways, Ramps, Runways	N/A

Other Items (that were observed)	N/A
---	------------