

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**  
Graham Prewett

**PROJECT:**  
Stockdale High School



**INSPECTION TYPE:**  
General Construction

**INSPECTOR :** FRANCISCO ROMERO  
**DATE :** SEPTEMBER 11, 2024  
**CITY :** BAKERSFIELD  
**STATE :** CALIFORNIA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# SUMMARY OF INSPECTION

<b>53</b> Items Inspected	<b>32</b> Satisfactory	<b>0</b> Unsatisfactory	<b>21</b> N/A
------------------------------	---------------------------	----------------------------	------------------

At my arrival to the site, Gabino was not available at the moment, but he allowed me to do inspection.

At my arrival to the site, I found workers wearing all their gear on site, shade was available and water was available as well, and ice for water to be cool while workers were on the roof.

I also verified all their tools and power cords and everything was in good Working condition

In addition I verified their IPP ( Which it was electronic, ) first aid kit and fire extinguisher and everything was in order.

I will provide report for their review.

# INSPECTION ITEMS

Documentation	
Site Contact	<b>Satisfactory</b>
Safety Program (Including IIPP)	<b>Satisfactory</b>
Heat Illness Prevention Program	<b>Satisfactory</b>
Safety Data Sheets	<b>Satisfactory</b>
Daily Inspections	<b>Satisfactory</b>
Tailgate Meetings	<b>Satisfactory</b>
Sub-Contractor Meetings	<b>N/A</b>
OSHA Permits	<b>Satisfactory</b>

<b>Labor Law Postings</b>	<b>Satisfactory</b>
---------------------------	---------------------

<b>Emergency / Other Postings</b>	<b>Satisfactory</b>
-----------------------------------	---------------------

<b>First Aid / CPR Certification</b>	<b>Satisfactory</b>
--------------------------------------	---------------------

## Emergency Items

<b>Access / Egress</b>	<b>Satisfactory</b>
------------------------	---------------------

<b>Elevator for Hoisting Workers (if needed)</b>	<b>N/A</b>
--	------------

<b>Fire Extinguisher(s)</b>	<b>Satisfactory</b>
-----------------------------	---------------------

<b>First Aid Kit(s)</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Comment</b>	
----------------	--

Found first aid kit available to workers and fully stocked	-
--	---

<b>Eye Wash Station</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Other Fire Fighting Equipment (If needed)</b>	<b>N/A</b>
--	------------

## General Items


<b>Restrooms</b>	<b>Satisfactory</b>
------------------	---------------------

<b>Hand Washing Stations</b>	<b>Satisfactory</b>
------------------------------	---------------------

<b>Waste Containers</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Potable Water</b>	<b>Satisfactory</b>
----------------------	---------------------

<b>Comment</b>	
----------------	--

<p>Water was available to all employees.</p>	
--	---

<p><b>Shade</b></p>	<p><b>Satisfactory</b></p>
---------------------	----------------------------

<p><b>Comment</b></p>	
-----------------------	--

<p>Shade was setting up on site for workers</p>	
---	--

**Tools & Equipment**

<p><b>Power Tools</b></p>	<p><b>Satisfactory</b></p>
---------------------------	----------------------------

<p><b>Comment</b></p>	
-----------------------	--

<p>Power and hand tools were inspected on site</p>	
--	---

<p><b>Hand Tools</b></p>	<p><b>Satisfactory</b></p>
--------------------------	----------------------------

<p><b>Powder Actuated Tools</b></p>	<p><b>Satisfactory</b></p>
-------------------------------------	----------------------------

<p><b>Pneumatic Nailers</b></p>	<p><b>N/A</b></p>
---------------------------------	-------------------

<b>Mobile Elevated Work Platforms (MEWP's)</b>	<b>N/A</b>
--	------------


<b>Powered Industrial Trucks</b>	<b>Satisfactory</b>
----------------------------------	---------------------

<b>Heavy Mobile Equipment (Excavators, Loaders, etc)</b>	<b>N/A</b>
--	------------

<b>Cranes</b>	<b>N/A</b>
---------------	------------


<b>Cylinder Storage</b>	<b>N/A</b>
-------------------------	------------

<b>Ladders</b>	<b>Satisfactory</b>
----------------	---------------------


<b>Comment</b>	
Ladder was inspected and it was secured to access the roof on site	

## Operations

<b>Personal Protective Equipment</b>	<b>Satisfactory</b>
--------------------------------------	---------------------

<b>Comment</b>	
Personal protection equipment was being worn by workers on site.	

<b>Trenching &amp; Excavation</b>	<b>N/A</b>
-----------------------------------	------------

<b>Fall Protection</b>	<b>Satisfactory</b>
<b>Guardrails</b>	<b>N/A</b>
<b>Floor / Wall Openings</b>	<b>N/A</b>
<b>Supported Scaffolding</b>	<b>N/A</b>
<b>Mobile Scaffolding</b>	<b>N/A</b>
<b>Suspended Scaffolding</b>	<b>N/A</b>
<b>Confined Spaces</b>	<b>N/A</b>
<b>Impalement Hazards</b>	<b>Satisfactory</b>
<b>Traffic Control</b>	<b>Satisfactory</b>
<b>Roofing Operations</b>	<b>Satisfactory</b>
<b>Housekeeping</b>	<b>Satisfactory</b>
<b>Comment</b>	
<p>Good housekeeping on site. All tools were in good condition and were away from dangers or creating danger for the workers</p>	
<b>Demolition</b>	<b>N/A</b>
<b>Silica Control</b>	<b>N/A</b>

<b>Rigging Operations</b>	<b>N/A</b>
<b>Hot Work</b>	<b>N/A</b>
<b>Electrical Safety</b>	<b>Satisfactory</b>
<b>Lockout / Tagout</b>	<b>Satisfactory</b>
<b>Stairways, Ramps, Runways</b>	<b>N/A</b>
<b>Other Items (that were observed)</b>	<b>N/A</b>