



# EQUIPMENT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Innovative Metal Industries, Inc.	<b>Type of Inspection:</b>	Scissor lift
<b>Project</b>	#4254 Apple - Ashburn	<b>Date of Inspection</b>	June 27, 2024
<b>Inspector Name</b>	Will Cherry	<b>Time of Inspection</b>	06:00 AM

## NOTES

15 Items Inspected	15 Satisfactory	0 Unsatisfactory	0 N/A
-----------------------	--------------------	---------------------	----------

## INSPECTION ITEMS

### General

Click "Satisfactory" and enter the model # in the comments section below	Satisfactory
<b>Comment</b>	
1126921	-

Is the owners manual in place?	Satisfactory
--------------------------------	--------------

Is the back up alarm or moving alarm working?	Satisfactory
---	--------------

Are the guardrails in place?	Satisfactory
------------------------------	--------------

Are the tires in safe condition?	Satisfactory
----------------------------------	--------------

Is the emergency stop button working?	Satisfactory
---------------------------------------	--------------

Are the indicator lights working?	Satisfactory
-----------------------------------	--------------

Does the platform extension open and close smoothly and lock into place?	Satisfactory
--	--------------

**Perform a platform control check. Does everything operate smoothly?**

**Satisfactory**

**Perform a ground control check. Does everything operate smoothly?**

**Satisfactory**

**Is the lift in overall good condition and the platform clean?**

**Satisfactory**

**Are the structure, pins, scissors and covers in good condition?**

**Satisfactory**

**Can you clearly see the capacity, weight and limits not the name plate or manufacturer decals?**

**Satisfactory**

**Does the horn work?**

**Satisfactory**

**Check the batteries. Is the water level sufficient?**

**Satisfactory**

