

SAFETY INSPECTION REPORT

CONDUCTED FOR:
Jim Crawford Construction

PROJECT:
Clovis USD District Office Expansion



INSPECTION TYPE:
General Construction

INSPECTOR : ESPITIA GUS
DATE : DECEMBER 06, 2024
CITY : CLOVIS
STATE : CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53 Items Inspected	22 Satisfactory	0 Unsatisfactory	31 N/A
------------------------------	---------------------------	----------------------------	------------------

Upon my arrival at the job site, I met with AJ. I inquired about the IIPP and safety programs binder, which were kept in the truck along with the first aid kit and fire extinguisher. AJ confirmed that he is conducting daily inspections and holding weekly tailgate meetings.

The crew was grading the ground in preparation for pouring concrete. All workers were wearing the required PPE. Drinking water was available in AJ's truck. The front loader operator was observed operating the equipment safely. Overall, the site had good housekeeping practices, and the restrooms were clean.

INSPECTION ITEMS

Documentation

Site Contact	Satisfactory
Comment	
I met with AJ at the job site, and was able to provide me with IIPP and safety binder	-

Safety Program (Including IIPP)

Satisfactory

Comment	
Safety Program is available	

Heat Illness Prevention Program

Satisfactory

Comment

<p>Heat Illness Prevention Program is available and site specific information is completed.</p>	
---	---

<p>Safety Data Sheets Satisfactory</p>	
<p style="text-align: center;">Comment</p>	
<p>SDS are available for employee access</p>	<p style="text-align: center;">-</p>

<p>Daily Inspections Satisfactory</p>	
<p style="text-align: center;">Comment</p>	
<p>AJ confirmed he is conducting the daily inspection</p>	<p style="text-align: center;">-</p>

<p>Tailgate Meetings Satisfactory</p>	
<p style="text-align: center;">Comment</p>	
<p>AJ confirmed they are conducting weekly tailgate meeting</p>	<p style="text-align: center;">-</p>

<p>Sub-Contractor Meetings N/A</p>	
---	--

<p>OSHA Permits Satisfactory</p>	
<p style="text-align: center;">Comment</p>	
<p>Permits are pulled by GC</p>	<p style="text-align: center;">-</p>

<p>Labor Law Postings N/A</p>	
--	--

<p>Emergency / Other Postings Satisfactory</p>	
<p style="text-align: center;">Comment</p>	

<p>Emergency medical provider’s information is available on the safety binder</p>	
---	---

<p>First Aid / CPR Certification Satisfactory</p>	
<p style="text-align: center;">Comment</p>	
<p>AJ is first aid and CPR certified</p>	<p style="text-align: center;">-</p>

Emergency Items


<p>Access / Egress N/A</p>

<p>Elevator for Hoisting Workers (if needed) N/A</p>

<p>Fire Extinguisher(s) Satisfactory</p>	
<p style="text-align: center;">Comment</p>	

<p>Fire extinguisher is readily available on site</p>	
---	---

<p>First Aid Kit(s) Satisfactory</p>	
<p style="text-align: center;">Comment</p>	

<p>First aid kit is fully replenished and readily available on site</p>	
---	---

<p>Eye Wash Station</p>	<p>Satisfactory</p>
--------------------------------	----------------------------

<p>Other Fire Fighting Equipment (If needed)</p>	<p>N/A</p>
---	-------------------


General Items

<p>Restrooms</p>	<p>Satisfactory</p>
<p>Comment</p>	
<p>Plenty of toilets are located on site and are being kept clean and in good working order.</p>	<p>-</p>

<p>Hand Washing Stations</p>	<p>Satisfactory</p>
<p>Comment</p>	
<p>Wash stations are clean and in sanitary condition. There is an adequate supply of soap and paper towels.</p>	<p>-</p>

<p>Waste Containers</p>	<p>Satisfactory</p>
<p>Comment</p>	
<p>Waste containers provided</p>	<p>-</p>

<p>Potable Water</p>	<p>Satisfactory</p>
<p>Comment</p>	

<p>Drinking water is available on site</p>	
--	---

<p>Shade</p>	<p>Satisfactory</p>
<p>Comment</p>	
<p>Structural shade is available onsite</p>	<p>-</p>

Tools & Equipment

<p>Power Tools</p>	<p>N/A</p>
---------------------------	-------------------

<p>Hand Tools</p>	<p>Satisfactory</p>
--------------------------	----------------------------

<p>Powder Actuated Tools</p>	<p>N/A</p>
-------------------------------------	-------------------


<p>Pneumatic Nailers</p>	<p>N/A</p>
---------------------------------	-------------------

<p>Mobile Elevated Work Platforms (MEWP's)</p>	<p>N/A</p>
---	-------------------

<p>Powered Industrial Trucks</p>	<p>N/A</p>
---	-------------------

<p>Heavy Mobile Equipment (Excavators, Loaders, etc)</p>	<p>Satisfactory</p>
---	----------------------------

<p>Comment</p>	
-----------------------	--

<p>Front loader operator was operating safely</p>	
---	---

Cranes	N/A
---------------	------------

Cylinder Storage	N/A
-------------------------	------------

Ladders	N/A
----------------	------------

Operations

Personal Protective Equipment	Satisfactory
--------------------------------------	---------------------

Comment

All PPE being worn



Trenching & Excavation	N/A
-----------------------------------	------------

Fall Protection	N/A
------------------------	------------

Guardrails	N/A
-------------------	------------

Floor / Wall Openings	N/A
------------------------------	------------

Supported Scaffolding	N/A
------------------------------	------------

Mobile Scaffolding	N/A
---------------------------	------------

Suspended Scaffolding	N/A
------------------------------	------------

Confined Spaces	N/A
------------------------	------------

Impalement Hazards	Satisfactory
Comment	
No impalement hazards during the safety inspection	-
Traffic Control	N/A
Roofing Operations	N/A
Housekeeping	Satisfactory
Comment	
Housekeeping in good shape.	-
Demolition	N/A
Silica Control	N/A
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	N/A
Lockout / Tagout	N/A
Stairways, Ramps, Runways	N/A
Other Items (that were observed)	N/A