

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**  
Jim Murray Roofing Inc.

**PROJECT:**  
ParkWear Apartment



**INSPECTION TYPE:**  
General Construction

**INSPECTOR :** STEVE HARRINGTON  
**DATE :** NOVEMBER 19, 2024  
**CITY :** IRVINE  
**STATE :** CALIFORNIA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# SUMMARY OF INSPECTION

**53**  
Items Inspected

**23**  
Satisfactory

**0**  
Unsatisfactory

**30**  
N/A

Job site was busted and reviewed for safe practices and conditions. Before walking the job I joined the guys in stretch and flex and fall protection equipment was inspected as part of the biannual inspections. Please see report for further details

## INSPECTION ITEMS

### Documentation

Site Contact


**Satisfactory**

Safety Program (Including IIPP)

**Satisfactory**

**Comment**

Mauricio has his iipp in his truck available for review




Heat Illness Prevention Program

**Satisfactory**


**Comment**

Heat illness prevention plan is on site in both English and Spanish



<b>Safety Data Sheets</b>	<b>N/A</b>
---------------------------	------------

<b>Daily Inspections</b>	<b>Satisfactory</b>
--------------------------	---------------------

<b>Comment</b>	
Job site inspections are being performed and documented. Underside of carports are also included in the inspection.	

<b>Tailgate Meetings</b>	<b>Satisfactory</b>
--------------------------	---------------------

<b>Comment</b>	
Tailgate meeting was held on hearing protection	

<b>Sub-Contractor Meetings</b>	<b>N/A</b>
--------------------------------	------------

<b>OSHA Permits</b>	<b>N/A</b>
---------------------	------------


<b>Labor Law Postings</b>	<b>Satisfactory</b>
---------------------------	---------------------

<b>Comment</b>	
Labor law posting are in place in common area at JMRI office	-

<b>Emergency / Other Postings</b>	<b>Satisfactory</b>
-----------------------------------	---------------------

<b>Comment</b>	

Maps and contact information for nearest hospitals and urgent care are in place



**First Aid / CPR Certification** **Satisfactory**

Comment	
The entire crew is certified in first aid and cpr	-

**Emergency Items**

**Access / Egress** **Satisfactory**

**Elevator for Hoisting Workers (if needed)** **N/A**

**Fire Extinguisher(s)** **Satisfactory**

**First Aid Kit(s)** **Satisfactory**

**Eye Wash Station** **N/A**

**Other Fire Fighting Equipment (If needed)** **N/A**

**General Items**

**Restrooms** **Satisfactory**

Comment	
Restrooms are available in pool area	-


**Hand Washing Stations** **Satisfactory**

**Waste Containers** **N/A**

**Potable Water** **Satisfactory**

**Comment**

Plenty of drinking water is on site



**Shade** **Satisfactory**

**Tools & Equipment**

**Power Tools** **Satisfactory**

**Comment**

Power tools are in good condition.



**Hand Tools** **Satisfactory**


**Comment**

Hand tools are free of damages




<b>Powder Actuated Tools</b>	<b>N/A</b>
<b>Pneumatic Nailers</b>	<b>N/A</b>
<b>Mobile Elevated Work Platforms (MEWP's)</b>	<b>N/A</b>
<b>Powered Industrial Trucks</b>	<b>N/A</b>
<b>Heavy Mobile Equipment (Excavators, Loaders, etc)</b>	<b>N/A</b>
<b>Cranes</b>	<b>N/A</b>
<b>Cylinder Storage</b>	<b>N/A</b>


<b>Ladders</b>	<b>Satisfactory</b>
----------------	---------------------

<b>Comment</b>	
Great job by Juan with holding ladder while Omar secures it.	

## Operations

<b>Personal Protective Equipment</b>	<b>Satisfactory</b>
--------------------------------------	---------------------

<b>Comment</b>	
Great job with PPE. Also please note battery powered blowers are being used on Western National properties	

<b>Trenching &amp; Excavation</b>	<b>N/A</b>
<b>Fall Protection</b>	<b>Satisfactory</b>
<b>Comment</b>	
Fall protection is on site, well maintained and available to use	
<b>Guardrails</b>	<b>N/A</b>
<b>Floor / Wall Openings</b>	<b>N/A</b>
<b>Supported Scaffolding</b>	<b>N/A</b>
<b>Mobile Scaffolding</b>	<b>N/A</b>
<b>Suspended Scaffolding</b>	<b>N/A</b>
<b>Confined Spaces</b>	<b>N/A</b>
<b>Impalement Hazards</b>	<b>N/A</b>
<b>Traffic Control</b>	<b>N/A</b>
<b>Roofing Operations</b>	<b>Satisfactory</b>
<b>Housekeeping</b>	<b>Satisfactory</b>
<b>Demolition</b>	<b>N/A</b>

<b>Silica Control</b>	<b>N/A</b>
<b>Rigging Operations</b>	<b>N/A</b>
<b>Hot Work</b>	<b>N/A</b>
<b>Electrical Safety</b>	<b>N/A</b>
<b>Lockout / Tagout</b>	<b>N/A</b>
<b>Stairways, Ramps, Runways</b>	<b>N/A</b>

<b>Other Items (that were observed)</b>	<b>Satisfactory</b>
---	---------------------

**Comment**

I participated on Stretch and flex with the group before starting work. I also discussed the importance of the stretch and flex program

