



# EQUIPMENT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Karsyn Construction	<b>Type of Inspection:</b>	Boom Lift
<b>Project</b>	CUSD District Campus	<b>Date of Inspection</b>	September 06, 2024
<b>Inspector Name</b>	Rodolfo Breceda	<b>Time of Inspection</b>	06:36 AM

## NOTES

14 Items Inspected	14 Satisfactory	0 Unsatisfactory	0 N/A
-----------------------	--------------------	---------------------	----------

## INSPECTION ITEMS

General	
Click "Satisfactory" and enter the boom lift model # in the comments below	Satisfactory
<b>Comment</b>	
GTH 5519	-
Is the lift in overall good condition and the platform clean?	Satisfactory
Are there full body harnesses available with the correct lanyard for those working in the basket?	Satisfactory
Are the indicator lights working?	Satisfactory
Perform a platform control check. Does everything operate smoothly?	Satisfactory
Perform a ground control check. Does everything operate smoothly?	Satisfactory
Are the tires in safe condition?	Satisfactory

**Are the platform anchor point(s) in place and clearly labeled?**

**Satisfactory**

**Are the guardrails and platform door in securely in place?**

**Satisfactory**

**Can you clearly see the capacity, weight and limits not the name plate or manufacturer decals?**

**Satisfactory**

**Is the owners manual in place?**

**Satisfactory**

**Are the structure, pins and covers in good condition?**

**Satisfactory**

**Does the horn work?**

**Satisfactory**

**Is the moving alarm working?**

**Satisfactory**

