



EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Karsyn Construction	Type of Inspection:	Fork Lift
Project	CUSD District Campus	Date of Inspection	October 03, 2024
Inspector Name	Arturo Zavala	Time of Inspection	06:49 AM

NOTES

19 Items Inspected	19 Satisfactory	0 Unsatisfactory	0 N/A
------------------------------	---------------------------	----------------------------	-----------------

INSPECTION ITEMS

General

Click "Satisfactory" and enter the fork lift model # in the comments below	Satisfactory
Comment	
Kubota	-
145 hours and 1/2 tank	-

Is the owners manual in place? **Satisfactory**

Is the seat belt in place and in safe condition? **Satisfactory**

Is the lift's weight capacity legible? **Satisfactory**

Is the manufacturer name plate in place and legible? **Satisfactory**

Do the fork controls operate smoothly and safely? **Satisfactory**

Do the lift's brakes work? **Satisfactory**

Does the emergency brake work? **Satisfactory**

If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturer's instructions?

Satisfactory

Is the mast securely in place?

Satisfactory

Are the fluid levels good? (oil, fuel, water, etc)

Satisfactory

Is the lift free of leaks?

Satisfactory

Are hoses and chains in safe condition?

Satisfactory

Does the horn work?

Satisfactory

Are the headlights and brake lights in good working order?

Satisfactory

Is the overheard guard securely in place and in safe condition?

Satisfactory

Are the forks in safe condition?

Satisfactory

Are the tires in safe condition?

Satisfactory

Is the lift in overall good condition?

Satisfactory

