

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Karsyn Construction	Type of Inspection:	Scaffolding
Project	Hirayama Elementary	Date of Inspection	October 14, 2024
Inspector Name	Angel Serafin-Sandoval	Time of Inspection	07:51 AM

NOTES							
15 Items Inspected	15 Satisfactory	0 Unsatisfactory	0 N/A				

INSPECTION ITEMS

General	
Are daily inspections being done by a competent person?	Satisfactory
Is the scaffold on a secure foundation?	Satisfactory
Are base plates installed and appropriately nailed to mud sills (if sills are required)?	Satisfactory
s the scaffold plumb and level?	Satisfactory
Are cross braces installed per the manufacturer and OSHA instructions?	Satisfactory
Are platforms fully planked with no more than a 1" gap between planks?	Satisfactory
Are planks in safe condition?	Satisfactory
Do planks overlap supports (or otherwise secured) per manufacturer and OSHA instructions?	Satisfactory

Are guardrails correctly installed on platforms above 6 feet? (Note: Some Mfg's require rails at any height)	Satisfactory
is there safe access to each working level of the scaffold?	Satisfactory
Are toe-boards installed where required, including above entranceways and where others may pass underneath?	Satisfactory
if more than four times the width of the base, is the scaffold braced per the manufacturer and OSHA instructions?	Satisfactory
Are only trained users being allowed on the scaffold?	Satisfactory
Are only competent, qualified persons erecting and dismantling scaffolding?	Satisfactory
Is the scaffold safe to use in every other way?	Satisfactory