



# EQUIPMENT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Karsyn Construction	<b>Type of Inspection:</b>	Fork Lift
<b>Project</b>	Hirayama	<b>Date of Inspection</b>	August 19, 2024
<b>Inspector Name</b>	Arturo Zavala	<b>Time of Inspection</b>	06:11 AM

## NOTES

19 Items Inspected	19 Satisfactory	0 Unsatisfactory	0 N/A
-----------------------	--------------------	---------------------	----------

## INSPECTION ITEMS

### General

Click "Satisfactory" and enter the fork lift model # in the comments below **Satisfactory**

Comment	
Kubota R430 123 hours	-

Is the owners manual in place? **Satisfactory**

Is the seat belt in place and in safe condition? **Satisfactory**

Is the lift's weight capacity legible? **Satisfactory**

Is the manufacturer name plate in place and legible? **Satisfactory**

Do the fork controls operate smoothly and safely? **Satisfactory**

Do the lift's brakes work? **Satisfactory**

Does the emergency brake work? **Satisfactory**

If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturer's instructions?

**Satisfactory**

Is the mast securely in place?

**Satisfactory**

Are the fluid levels good? (oil, fuel, water, etc)

**Satisfactory**

**Comment**

1/2 tank

-

Is the lift free of leaks?

**Satisfactory**

Are hoses and chains in safe condition?

**Satisfactory**

Does the horn work?

**Satisfactory**

Are the headlights and brake lights in good working order?

**Satisfactory**

Is the overhead guard securely in place and in safe condition?

**Satisfactory**

Are the forks in safe condition?

**Satisfactory**

Are the tires in safe condition?

**Satisfactory**

Is the lift in overall good condition?

**Satisfactory**

