

EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Karsyn Construction	Type of Inspection:	Skid Steer
Project	Santa Teresa	Date of Inspection	June 05, 2024
Inspector Name	Irving Serafin	Time of Inspection	06:12 AM

NOTES						
24	24	0	0			
Items Inspected	Satisfactory	Unsatisfactory	N/A			

INSPECTION ITEMS

General

Click "Satisfactory" and enter the skid steer model # in the comments below

Satisfactory

_

Comment

Kubota R420S

Hour meter reading available? (Enter reading in comments below	w) Satisfactory
Comment	
1979.4	-

Is the ignition and electrical system working correctly? Are all gauges and instruments visible and working correctly?	Satisfactory
Are the warning lights (and lights, if applicable) working correctly?	Satisfactory
Are the brakes working correctly?	Satisfactory
Is the moving alarm audible and working correctly?	Satisfactory
Does the engine sound normal?	Satisfactory

Do the steering controls all work normally, including response time?	Satisfactory
Is the instrumentation operating normally and legible?	Satisfactory
Do the levers (switches, toggles, joysticks, sticks, etc) work smoothly and safely?	Satisfactory
Is the exhaust in a safe condition with no excessive smoke, sparks or flames?	Satisfactory
Are the safety decks / warning stickers visible and legible?	Satisfactory
Is the operators manual in place?	Satisfactory
Is the air filter free of dust and trash build up?	Satisfactory
Is the chassis free of structural damage? Is the turntable lubricated?	Satisfactory
Is the bucket and teeth in safe condition free of structural damage and/or wear?	Satisfactory
Is the coolant system free of leaks and damage? is the coolant level good?	Satisfactory
Is the engine oil level good? Are there any leaks?	Satisfactory
Are the engine belts free of wear and damage?	Satisfactory
Is the fuel system in good condition, including the fuel level?	Satisfactory
Comment -	
Is the hydraulic system in good condition? Are the hydraulic level and filters good?	Satisfactory

Are the tracks / wheels in good condition and free of wear and damage?

Satisfactory

Is the operator cab clean, items secure, and free of damage?

Satisfactory

Satisfactory

Karsyn Construction | Santa Teresa