

EQUIPMENT INSPECTION

Gen	erated by Safety Compliance A	App www.safetycompliance.	com www.safetycor	nplianceapp.com	
Company	Karsyn Construction	Type of Inspection:	Scissor lift		
Project	Selma roof access	Date of Inspection	February 12, 2025		
Inspector Name	Nick Watts	Time of Inspection	08:45 AM		
		NOTES			
lte	15 ems Inspected	14 Satisfactory	1 Unsatisfactory	0 N/A	
INSPECTION ITEMS					
General					
Click "Satisfa	Unsatisfactory				
	Comment				
Skyjack SJIII	3226 A		-		
Will not lower			-		
Is the owners manual in place?				Satisfactory	
Is the back up alarm or moving alarm working?				Satisfactory	
Are the guardrails in place?				Satisfactory	
Are the tires i	n safe condition?			Satisfactory	
Is the emergency stop button working?				Satisfactory	
Are the indica	ator lights working?			Satisfactory	
Does the platform extension open and close smoothly and lock into place?				Satisfactory	

Perform a platform control check. Does everything operate smoothly?	Satisfactory
Perform a ground control check. Does everything operate smoothly?	Satisfactory
Is the lift in overall good condition and the platform clean?	Satisfactory
Are the structure, pins, scissors and covers in good condition?	Satisfactory
Can you clearly see the capacity, weight and limits not the name plate or manufacturer decals?	Satisfactory
Does the horn work?	Satisfactory
Check the batteries. Is the water level sufficient?	Satisfactory