

## **PROJECT INSPECTION**

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

	erated by Safety Compliance App www.s	arety compliance.co	mi   www.saietycom	рпапсеарр.сотт	
Company	Karsyn Construction	Type of Inspection:	Scaffolding		
Project	Shields & Brawley Elementary	Date of Inspection	August 21, 2024		
Inspector Name	Irving Serafin	Time of Inspection	09:50 AM		
NOTES					
lte	15	15	<b>0</b> nsatisfactory	<b>0</b> N/A	
INSPECTION ITEMS					
General					
Are daily insp	Satisfactory				
Comment					
Andrew -					
Is the scaffold	Satisfactory				
Are base plat	Satisfactory				
s the scaffold plumb and level?				Satisfactory	
Are cross braces installed per the manufacturer and OSHA instructions?				Satisfactory	
Are platforms	Satisfactory				
Are planks in safe condition?				Satisfactory	

Do planks overlap supports (or otherwise secured) per manufacturer and OSHA instructions?	Satisfactory
Are guardrails correctly installed on platforms above 6 feet? (Note: Some Mfg's require rails at any height)	Satisfactory
is there safe access to each working level of the scaffold?	Satisfactory
Are toe-boards installed where required, including above entranceways and where others may pass underneath?	Satisfactory
if more than four times the width of the base, is the scaffold braced per the manufacturer and OSHA instructions?	Satisfactory
Are only trained users being allowed on the scaffold?	Satisfactory
Comment	
Indemnity agreement signed by all other trades using our scaffold.	
Are only competent, qualified persons erecting and dismantling scaffolding?	Satisfactory
Is the scaffold safe to use in every other way?	Satisfactory