

## **EQUIPMENT INSPECTION**

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

		,		i i i i i i i i i i i i i i i i i i i		
Company	Karsyn Construction	Type of Inspection:	Scissor lift			
Project	Terry Bradley Ed Center	Date of Inspection	October 02, 2024			
Inspector Name	Nick Watts	Time of Inspection	06:18 AM			
NOTES						
lte	15 ems Inspected	<b>15</b> Satisfactory	<b>0</b> Unsatisfactory	<b>0</b> N/A		
INSPECTION ITEMS						
General						
Click "Satisfactory" and enter the model # in the comments section below				Satisfactory		
	Comment					
MEC			-			
Is the owners manual in place?				Satisfactory		
Is the back up alarm or moving alarm working?				Satisfactory		
Are the guardrails in place?				Satisfactory		
Are the tires in safe condition?				Satisfactory		
Is the emergency stop button working?				Satisfactory		
Are the indica	ator lights working?			Satisfactory		
Dana (Laure)	famma and an allow a construction 1		:(l0			
Does the platform extension open and close smoothly and lock into place?				Satisfactory		

Perform a platform control check. Does everything operate smoothly?	Satisfactory
Perform a ground control check. Does everything operate smoothly?	Satisfactory
Is the lift in overall good condition and the platform clean?	Satisfactory
Are the structure, pins, scissors and covers in good condition?	Satisfactory
Can you clearly see the capacity, weight and limits not the name plate or manufacturer decals?	Satisfactory
Does the horn work?	Satisfactory
Check the batteries. Is the water level sufficient?	Satisfactory