

EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

	crated by Carety Compliance App	www.sarctycompnance	ioom www.saretyoo.	прианосарриоси	
Company	Karsyn Construction	Type of Inspection:	Scissor lift		
Project	Terry Bradley Ed Center	Date of Inspection	October 16, 2024		
Inspector Name	Nick Watts	Time of Inspection	06:29 AM		
NOTES					
lte	15 ems Inspected	15 Satisfactory	0 Unsatisfactory	0 N/A	
INSPECTION ITEMS					
General					
Click "Satisfactory" and enter the model # in the comments section below				Satisfactory	
	Comment				
MEC			_		
0					
Is the owners	manual in place?			Satisfactory	
Is the back up alarm or moving alarm working?				Satisfactory	
Are the guardrails in place?				Satisfactory	
Are the tires i	in safe condition?			Satisfactory	
Is the emergency stop button working?				Satisfactory	
Are the indica	ator lights working?			Satisfactory	
Does the platform extension open and close smoothly and lock into place?				Satisfactory	

Perform a platform control check. Does everything operate smoothly?	Satisfactory
Perform a ground control check. Does everything operate smoothly?	Satisfactory
Is the lift in overall good condition and the platform clean?	Satisfactory
Are the structure, pins, scissors and covers in good condition?	Satisfactory
Can you clearly see the capacity, weight and limits not the name plate or manufacturer decals?	Satisfactory
Does the horn work?	Satisfactory
Check the batteries. Is the water level sufficient?	Satisfactory