



# EQUIPMENT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Karsyn Construction	<b>Type of Inspection:</b>	Scissor lift
<b>Project</b>	Terry Bradley Ed Center	<b>Date of Inspection</b>	December 03, 2024
<b>Inspector Name</b>	Nick Watts	<b>Time of Inspection</b>	05:59 AM

## NOTES

15 Items Inspected	14 Satisfactory	1 Unsatisfactory	0 N/A
-----------------------	--------------------	---------------------	----------

## INSPECTION ITEMS

### General

Click "Satisfactory" and enter the model # in the comments section below	Unsatisfactory
Comment	
MEC 4046	-
Unable to use due to a bad charger	-

Is the owners manual in place? **Satisfactory**

Is the back up alarm or moving alarm working? **Satisfactory**

Are the guardrails in place? **Satisfactory**

Are the tires in safe condition? **Satisfactory**

Is the emergency stop button working? **Satisfactory**

Are the indicator lights working? **Satisfactory**

Does the platform extension open and close smoothly and lock into place? **Satisfactory**

**Perform a platform control check. Does everything operate smoothly?**

**Satisfactory**

**Perform a ground control check. Does everything operate smoothly?**

**Satisfactory**

**Is the lift in overall good condition and the platform clean?**

**Satisfactory**

**Are the structure, pins, scissors and covers in good condition?**

**Satisfactory**

**Can you clearly see the capacity, weight and limits not the name plate or manufacturer decals?**

**Satisfactory**

**Does the horn work?**

**Satisfactory**

**Check the batteries. Is the water level sufficient?**

**Satisfactory**

