



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

| | | | |
|-----------------------|-------------------------|----------------------------|-------------------|
| Company | Karsyn Construction | Type of Inspection: | Cal/OSHA Scaffold |
| Project | Terry Bradley Ed Center | Date of Inspection | January 03, 2025 |
| Inspector Name | Nick Watts | Time of Inspection | 09:30 AM |

NOTES

| | | | |
|------------------------------|---------------------------|----------------------------|-----------------|
| 16 Items Inspected | 16 Satisfactory | 0 Unsatisfactory | 0 N/A |
|------------------------------|---------------------------|----------------------------|-----------------|

INSPECTION ITEMS

General

Are erectors and dismantlers under the supervision of a qualified erector? **Satisfactory**

Is the scaffold safe to use in every other way? **Satisfactory**

Are only trained users being allowed on the scaffold? **Satisfactory**

if more than three times the width of the base, is the scaffold braced per the manufacturer and OSHA instructions? **Satisfactory**

Are toe-boards installed where required, including above entranceways and where others may pass underneath? **Satisfactory**

is there safe access to each working level of the scaffold? **Satisfactory**

Are guardrails correctly installed on platforms above 7 1/2 feet? (Note: Some Mfg's require rails at any height) **Satisfactory**

Do planks overlap supports (or otherwise secured) per manufacturer and OSHA instructions? **Satisfactory**

Are planks in safe condition?

Satisfactory

Are platforms fully planked with no more than a 1" gap between planks?

Satisfactory

Are cross braces installed per the manufacturer and OSHA instructions?

Satisfactory

Is the scaffold plumb and level?

Satisfactory

Are base plates installed and appropriately nailed to mud sills (if sills are required)?

Satisfactory

Is the scaffold on a secure foundation?

Satisfactory

If over 36 feet or 3 stories, has an OSHA permit for scaffolding been pulled and notification of activity given to the local OSHA office?

Satisfactory

Are daily inspections being done by a competent person?

Satisfactory