

EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

	erated by Sarety Compliance App	W W W.56	netycomphance	.com www.saletycom	ірпапсеарр.сопі		
Company	Karsyn Construction		Type of Inspection:	Scissor lift			
Project	Terry Bradley Ed Center		Date of Inspection	January 13, 2025			
Inspector Name	Nick Watts		Time of Inspection	06:46 AM			
NOTES							
lte	15 ems Inspected		15 sfactory	0 Unsatisfactory	0 N/A		
INSPECTION ITEMS							
General							
Click "Satisfa	Satisfactory						
Comment							
MEC 4046 -							
Is the owners manual in place?					Satisfactory		
Is the back up alarm or moving alarm working?					Satisfactory		
Are the guardrails in place?					Satisfactory		
Are the tires i	n safe condition?				Satisfactory		
Is the emergency stop button working?					Satisfactory		
Are the indica	ator lights working?				Satisfactory		
Does the platform extension open and close smoothly and lock into place?					Satisfactory		

Perform a platform control check. Does everything operate smoothly?	Satisfactory
Perform a ground control check. Does everything operate smoothly?	Satisfactory
Is the lift in overall good condition and the platform clean?	Satisfactory
Are the structure, pins, scissors and covers in good condition?	Satisfactory
Can you clearly see the capacity, weight and limits not the name plate or manufacturer decals?	Satisfactory
Does the horn work?	Satisfactory
Check the batteries. Is the water level sufficient?	Satisfactory