

EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

| Gen | erated by Safety Compliance A | pp www.safetycompliance.c | om www.safetycon | nplianceapp.com | |
|--|-------------------------------|---------------------------|----------------------------|-----------------|--|
| Company | Karsyn Construction | Type of Inspection: | Scissor lift | | |
| Project | Terry Bradley Ed Center | Date of Inspection | January 16, 2025 | | |
| Inspector Name | Nick Watts | Time of Inspection | 08:44 AM | | |
| NOTES | | | | | |
| lte | 15 ems Inspected | 15 Satisfactory | 0 Insatisfactory | 0 N/A | |
| INSPECTION ITEMS | | | | | |
| General | | | | | |
| Click "Satisfa | Satisfactory | | | | |
| | Comment | | | | |
| MEC 4046 | | | - | | |
| Is the owners manual in place? | | | | Satisfactory | |
| Is the back up alarm or moving alarm working? | | | | Satisfactory | |
| Are the guardrails in place? | | | | Satisfactory | |
| Are the tires in safe condition? | | | | Satisfactory | |
| Is the emergency stop button working? | | | | Satisfactory | |
| Are the indicator lights working? | | | | Satisfactory | |
| Does the platform extension open and close smoothly and lock into place? | | | | Satisfactory | |

| Perform a platform control check. Does everything operate smoothly? | Satisfactory |
|--|--------------|
| Perform a ground control check. Does everything operate smoothly? | Satisfactory |
| Is the lift in overall good condition and the platform clean? | Satisfactory |
| Are the structure, pins, scissors and covers in good condition? | Satisfactory |
| Can you clearly see the capacity, weight and limits not the name plate or manufacturer decals? | Satisfactory |
| Does the horn work? | Satisfactory |
| Check the batteries. Is the water level sufficient? | Satisfactory |