



# EQUIPMENT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Karsyn Construction	<b>Type of Inspection:</b>	Scissor lift
<b>Project</b>	Terry Bradley Ed Center	<b>Date of Inspection</b>	January 21, 2025
<b>Inspector Name</b>	Nick Watts	<b>Time of Inspection</b>	08:27 AM

## NOTES

15 Items Inspected	15 Satisfactory	0 Unsatisfactory	0 N/A
-----------------------	--------------------	---------------------	----------

## INSPECTION ITEMS

### General

Click "Satisfactory" and enter the model # in the comments section below	Satisfactory
<b>Comment</b>	
MEC 4046	-

Is the owners manual in place?	Satisfactory
Is the back up alarm or moving alarm working?	Satisfactory
Are the guardrails in place?	Satisfactory
Are the tires in safe condition?	Satisfactory
Is the emergency stop button working?	Satisfactory
Are the indicator lights working?	Satisfactory
Does the platform extension open and close smoothly and lock into place?	Satisfactory

**Perform a platform control check. Does everything operate smoothly?**

**Satisfactory**

**Perform a ground control check. Does everything operate smoothly?**

**Satisfactory**

**Is the lift in overall good condition and the platform clean?**

**Satisfactory**

**Are the structure, pins, scissors and covers in good condition?**

**Satisfactory**

**Can you clearly see the capacity, weight and limits not the name plate or manufacturer decals?**

**Satisfactory**

**Does the horn work?**

**Satisfactory**

**Check the batteries. Is the water level sufficient?**

**Satisfactory**

