

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**  
Karsyn Construction

**PROJECT:**  
Terry Bradley School



**INSPECTION TYPE:**  
General Construction

**INSPECTOR :** KIM BURGESS  
**DATE :** JULY 23, 2024  
**CITY :** CLOVIS  
**STATE :** CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# SUMMARY OF INSPECTION


<b>53</b> Items Inspected	<b>33</b> Satisfactory	<b>1</b> Unsatisfactory	<b>19</b> N/A
------------------------------	---------------------------	----------------------------	------------------

Met Stan at seatrain. Reviewed documents. Labor law posters, annual height permit, emergency postings all present. Reviewed IIPP on site. Filled out all forms. Due to high heat temperatures, water supply and shade were in compliance. Good job today. Corrections on site: Backboards set when cutting material. Updated forms. Fire extinguishers were marked when needed. Please review report for photos and corrections made.

## INSPECTION ITEMS

### Documentation

<b>Site Contact</b>	<b>Satisfactory</b>
<b>Safety Program (Including IIPP)</b>	
<b>Comment</b>	<b>Satisfactory</b>
Updated all forms in IIPP.	-

<b>Heat Illness Prevention Program</b>	<b>Satisfactory</b>
<b>Comment</b>	
Heat illness program set in IIPP.	

<b>Safety Data Sheets</b>	<b>Satisfactory</b>
<b>Comment</b>	
Safety data sheets on site.	-

<b>Daily Inspections</b>	<b>Satisfactory</b>
--------------------------	---------------------

<b>Tailgate Meetings</b>	<b>Satisfactory</b>
--------------------------	---------------------

<b>Sub-Contractor Meetings</b>	<b>N/A</b>
--------------------------------	------------

<b>OSHA Permits</b>	<b>Satisfactory</b>
<b>Comment</b>	
Annual permit on site	

<b>Labor Law Postings</b>	<b>Satisfactory</b>
<b>Comment</b>	
2024 labor law posters visible in seatrain.	-

<b>Emergency / Other Postings</b>	<b>Satisfactory</b>
<b>Comment</b>	
Postings present	

<b>First Aid / CPR Certification</b>	<b>N/A</b>
--------------------------------------	------------

**Emergency Items**

<b>Access / Egress</b>	<b>Satisfactory</b>
------------------------	---------------------

<b>Elevator for Hoisting Workers (if needed)</b>	<b>N/A</b>
--	------------

<b>Fire Extinguisher(s)</b>	<b>Satisfactory</b>
<b>Comment</b>	
Checked all fire extinguishers. Inspections completed.	-

<b>First Aid Kit(s)</b>	<b>Satisfactory</b>
<b>Comment</b>	
First aid kit fully stocked.	-

<b>Eye Wash Station</b>	<b>N/A</b>
-------------------------	------------

<b>Other Fire Fighting Equipment (If needed)</b>	<b>N/A</b>
--	------------

## General Items

<b>Restrooms</b>	<b>Satisfactory</b>
------------------	---------------------

<b>Hand Washing Stations</b>	<b>Satisfactory</b>
------------------------------	---------------------

<b>Waste Containers</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Potable Water</b>	<b>Satisfactory</b>
<b>Comment</b>	
Cases of water in seatrain	-

<b>Shade</b>	<b>Satisfactory</b>
<b>Comment</b>	
Shade area set for workers.	-

## Tools & Equipment

<b>Power Tools</b>	<b>Satisfactory</b>
--------------------	---------------------

Comment	
Saws in good condition.	-

<b>Hand Tools</b>	<b>Satisfactory</b>
Comment	
Hand tools in compliance. Tools storage good.	-

<b>Powder Actuated Tools</b>	<b>Satisfactory</b>
------------------------------	---------------------

<b>Pneumatic Nailers</b>	<b>Satisfactory</b>
--------------------------	---------------------

<b>Mobile Elevated Work Platforms (MEWP's)</b>	<b>N/A</b>
--	------------

<b>Powered Industrial Trucks</b>	<b>N/A</b>
----------------------------------	------------

<b>Heavy Mobile Equipment (Excavators, Loaders, etc)</b>	<b>N/A</b>
--	------------


<b>Cranes</b>	<b>N/A</b>
---------------	------------

<b>Cylinder Storage</b>	<b>N/A</b>
-------------------------	------------

<b>Ladders</b>	<b>Satisfactory</b>
Comment	
No workers on ladders during inspection.	-

## Operations

<b>Personal Protective Equipment</b>	<b>Satisfactory</b>
Comment	

<p>All workers wearing hard hats. Eye protection and ear protection in place.</p>	
---	---

<p><b>Trenching &amp; Excavation</b></p>	<p><b>N/A</b></p>
--	-------------------

<p><b>Fall Protection</b></p>	<p><b>N/A</b></p>
-------------------------------	-------------------

<p><b>Guardrails</b></p>	<p><b>Satisfactory</b></p>
--------------------------	----------------------------

<p><b>Floor / Wall Openings</b></p>	<p><b>Satisfactory</b></p>
-------------------------------------	----------------------------

<p><b>Supported Scaffolding</b></p>	<p><b>N/A</b></p>
-------------------------------------	-------------------

<p><b>Mobile Scaffolding</b></p>	<p><b>Satisfactory</b></p>
----------------------------------	----------------------------

<p><b>Suspended Scaffolding</b></p>	<p><b>N/A</b></p>
-------------------------------------	-------------------

<p><b>Confined Spaces</b></p>	<p><b>N/A</b></p>
-------------------------------	-------------------

<p><b>Impalement Hazards</b></p>	<p><b>Satisfactory</b></p>
----------------------------------	----------------------------

<p><b>Comment</b></p>	
<p>No impalement hazards viewed</p>	<p>-</p>

<p><b>Traffic Control</b></p>	<p><b>N/A</b></p>
-------------------------------	-------------------

<p><b>Roofing Operations</b></p>	<p><b>N/A</b></p>
----------------------------------	-------------------

<p><b>Housekeeping</b></p>	<p><b>Satisfactory</b></p>
----------------------------	----------------------------

<p><b>Comment</b></p>	
-----------------------	--


Karsyn housekeeping very good.	-
--------------------------------	---

<b>Demolition</b>	<b>N/A</b>
-------------------	------------

<b>Silica Control</b>	<b>Satisfactory</b>
-----------------------	---------------------

<b>Rigging Operations</b>	<b>N/A</b>
---------------------------	------------

<b>Hot Work</b>	<b>Satisfactory</b>
-----------------	---------------------

<b>Comment</b>	
Hot work permit in place. Face shields and fire extinguishers present.	

<b>Electrical Safety</b>	<b>Satisfactory</b>
--------------------------	---------------------

<b>Lockout / Tagout</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Comment</b>	
Lockout tag out in place if needed.	

<b>Stairways, Ramps, Runways</b>	<b>Satisfactory</b>
----------------------------------	---------------------

<b>Other Items (that were observed)</b>	<b>Unsatisfactory</b>
---	-----------------------

<b>Comment</b>	
----------------	--

Backboard not in place . Was corrected on site.

