



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Legacy Construction	Type of Inspection:	General Construction
Project	22-045 Dr. Paz Visalia	Date of Inspection	January 16, 2025
Inspector Name	Luis Aguilar	Time of Inspection	07:38 AM

NOTES

19 Items Inspected	13 Satisfactory	0 Unsatisfactory	6 N/A
------------------------------	---------------------------	----------------------------	-----------------

INSPECTION ITEMS

General

Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)? **Satisfactory**

Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings) **Satisfactory**

Is drinking water and shade set up sufficient for the amount of workers? **Satisfactory**

Are emergency and labor law postings in place? **Satisfactory**

Is Personal Protective Equipment being worn as required? **Satisfactory**

Are scaffolding safety procedures being followed? **N/A**

Are hand and power tools being used safely? **Satisfactory**

Is good housekeeping being maintained? **Satisfactory**

Is fall protection in place where required? **Satisfactory**

Is trenching & excavation work being done safely?	N/A
Are confined space safety procedures being followed?	N/A
Are scissor lifts / elevated platforms being used safely?	N/A
Are boom lifts and other aerial devices being used safely?	N/A
Is heavy equipment being used safely?	N/A
Are electrical items being used safely?	Satisfactory
Are roofing operations being performed safely?	Satisfactory
Is demolition work being done safely?	Satisfactory
Are all other tasks being performed safely?	Satisfactory
Any other items?	Satisfactory