

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Gen	erated by Safety Compliance i	App www.sai	etycomphanc	e.com www.saletycom	прпапсеарр.соп	
Company	Legacy Construction		Type of Inspection:	Framing Inspection		
Project	22-049 UHC Bullard TI		Date of Inspection	July 01, 2024		
Inspector Name	Aaron Hernandez		Time of Inspection	06:05 AM		
NOTES						
lte	14 ems Inspected	Satis	7 factory	0 Unsatisfactory	7 N/A	
INSPECTION ITEMS						
General						
Are air compressors and generators set up safely?					N/A	
Are nail guns being used safely?					N/A	
Are hole and wall openings protected per OSHA regulations?					N/A	
Are stairways in place as required?					N/A	
If personal fall restraint / arrest systems are being used, are the anchors and lanyards set up correctly?					N/A	
is emergency equipment, including first aid kits and fire extinguishers available?					Satisfactory	
Are emergency and labor law postings in place?					Satisfactory	
Is scaffolding set up correctly and being used safely?					N/A	
Is fall protection in place where required?					N/A	

Is all required PPE being worn including hard hats and eye protection?	Satisfactory
Are electrical cords and other electrical related items in safe condition?	Satisfactory
Are hand and power tools being used safely?	Satisfactory
Is the company safety manual on site?	Satisfactory
Are SDS on site and available to employees?	Satisfactory