

## **PROJECT INSPECTION**

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Gen	erated by Safety Compliance	App www.safetycompliance	e.com   www.saretycor	npilanceapp.com
Company	Legacy Construction	Type of Inspection:	General Construction	on
Project	23-017 UHC Delano	Date of Inspection	February 19, 2025	
nspector Name	Josh Collins	Time of Inspection	03:25 PM	
		NOTES		
lte	19 ems Inspected	11 Satisfactory	2 Unsatisfactory	<b>6</b> N/A
	INS	SPECTION ITE	MS	
General				l
Is emergency	Satisfactory			
Is safety docu Meetings)	Satisfactory			
Is drinking wa	Satisfactory			
Are emergency and labor law postings in place?				Satisfactory
Is Personal P	Satisfactory			
Are scaffoldir	N/A			
Are hand and	power tools being used	safely?		Unsatisfactory
	Comment			
	ound in the chop saw for the he guard to make repeat cuts		-	

Is good housekeeping being maintained?	Satisfactory
Is fall protection in place where required?	Unsatisfactory
Comment	
The chain on the back of a scissor lift was not attached while being operated.	-
Is trenching & excavation work being done safely?	Satisfactory
Are confined space safety procedures being followed?	N/A
Are scissor lifts / elevated platforms being used safely?	Satisfactory
Are boom lifts and other aerial devices being used safely?	N/A
Is heavy equipment being used safely?	Satisfactory
Are electrical items being used safely?	Satisfactory
Are roofing operations being performed safely?	N/A
Is demolition work being done safely?	N/A
Are all other tasks being performed safely?	Satisfactory
Any other items?	N/A