SAFETY INSPECTION REPORT

CONDUCTED FOR: Lennar Homes of California, LLC

> PROJECT: Maggiore



INSPECTION TYPE: General Construction

INSPECTOR: JORDAN DUZI DATE: JANUARY 29, 2025 CITY: MOUNTAIN HOUSE STATE: CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION			
53	34	1	18
Items Inspected	Satisfactory	Unsatisfactory	N/A

Site was in good overall condition. Both models and production were active.

Roofers were correctly tied off while unloading materials on second story - Citadel.

Access ladders secured

- Ind truck operator loading roofing material was told to put seat belt on. Citadel
- DH Smith scaffold in good overall condition 9055 missing a toe board.
- 9066 missing portion of scaffold on roof area
- Tapers have dismantled mobile scaffolds
- Hand rails were installed in stairwells
- Railing installed throughout low windows
- Housekeeping in good overall condition
- PPE being worn including eye protection with power saws

INSPECTION ITEMS

Documentation	
Site Contact	Satisfactory
Comment	
Daniel Pereira	-
Safety Program (Including IIPP)	Satisfactory
Comment	

Safety Manual is on site

-

-

Heat Illness Prevention Program	Satisfactory
Safety Data Sheets	Satisfactory
Comment	
Should be available digitally	-
Daily Inspections	Satisfactory
Comment	
To be completed and filed	-
Tailgate Meetings	Satisfactory
Comment	
To be completed every ten days	-
Sub-Contractor Meetings	N/A
OSHA Permits	N/A
Labor Law Postings	Satisfactory
Comment	
Posted in trailer - to be checked next site visit	-

Emergency / Other Postings	Satisfactory
Comment	
Following postings should be up - to be checked in January. Map to nearest hospital, evacuation map, codes of safe practice, industrial truck and emergency numbers.	-
First Aid / CPR Certification	Satisfactory
Comment	

Up to date

N/A

Emergency Items	
Access / Egress	Satisfactory
Comment	
Access was compliant	-
Elevator for Hoisting Workers (if needed)	N/A

Fire Extinguisher(s)	Satisfactory
Comment	
To be present in trailer. Ensure it///s charged and being signed off monthly via inspection tag	-

First Aid Kit(s)	Satisfactory
Comment	
In trailer	-
Eye Wash Station	N/A

General Items	
Restrooms	Satisfactory
Comment	
Present and in good condition	-
Hand Washing Stations	Satisfactory
Waste Containers	Satisfactory
Potable Water	Satisfactory
Shade	Satisfactory
Comment	

-

Permanent structure provides shade

Power Tools	Satisfactory
Comment	
Saw guards in place	-
Hand Tools	Satisfactory
Powder Actuated Tools	Satisfactory
Pneumatic Nailers	Satisfactory
Comment	
Framers had safety glasses on with nail guns	-
Mobile Elevated Work Plarforms (MEWP's)	N/A
Powered Industrial Trucks	Unsatisfactor
Comment	Citadel
Ind truck operator corrected on site and told to secure seat belt	-
Heavy Mobile Equipment (Excavators, Loaders, etc)	Satisfactory
Cranes	N/A
Cylinder Storage	N/A
Ladders	Satisfactory
Comment	

Operations

Personal Protective Equipment	Satisfactory
-------------------------------	--------------

Tapers have dismantled mobile scaffolds

ennar nomes of Camornia, ELC Maggiore	Jan 29, 20/
Comment	
PPE being worn	-
Trenching & Excavation	N/A
Fall Protection	Satisfactory
Comment	
No fall protection violations	-
Guardrails	Satisfactory
Comment	
Railing installed within stairwells	-
Floor / Wall Openings	Satisfactory
Comment	
Low windows had railing installed	-
Supported Scaffolding	Satisfactory
Comment	DH Smith
Good overall condition but see notes in the summary for some one offs	-
Mobile Scaffolding	Satisfactory
Comment	

Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Traffic Control	N/A

-

Poofing Operations	Satisfactory
Roofing Operations	Satisfactory
Comment	Citadel
Roofers were correctly tied off	-
Housekeeping	Satisfactory
Comment	
Good overall housekeeping	-
Demolition	N/A
Silica Control	N/A
Comment	
No silica violations observed	-
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	Satisfactory
Comment	
Cords in good condition	-
Lockout / Tagout	N/A
Stairways, Ramps, Runways	Satisfactory
Other Items (that were observed)	N/A