



# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Mark Wilson Construction, Inc	<b>Type of Inspection:</b>	General Construction
<b>Project</b>	CCMC - Wound Care	<b>Date of Inspection</b>	December 12, 2024
<b>Inspector Name</b>	Jason Clark	<b>Time of Inspection</b>	04:05 PM

## NOTES

19  
Items Inspected

8  
Satisfactory

0  
Unsatisfactory

11  
N/A

2) Fresno Plumbing - Continue working on new waste lines.

## INSPECTION ITEMS

### General

Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)? **Satisfactory**

Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings) **Satisfactory**

Is drinking water and shade set up sufficient for the amount of workers? **Satisfactory**

Are emergency and labor law postings in place? **Satisfactory**

Is Personal Protective Equipment being worn as required? **Satisfactory**

Are scaffolding safety procedures being followed? **N/A**

Are hand and power tools being used safely? **Satisfactory**

Is good housekeeping being maintained? **Satisfactory**

<b>Is fall protection in place where required?</b>	<b>N/A</b>
<b>Is trenching &amp; excavation work being done safely?</b>	<b>N/A</b>
<b>Are confined space safety procedures being followed?</b>	<b>N/A</b>
<b>Are scissor lifts / elevated platforms being used safely?</b>	<b>N/A</b>
<b>Are boom lifts and other aerial devices being used safely?</b>	<b>N/A</b>
<b>Is heavy equipment being used safely?</b>	<b>N/A</b>
<b>Are electrical items being used safely?</b>	<b>N/A</b>
<b>Are roofing operations being performed safely?</b>	<b>N/A</b>
<b>Is demolition work being done safely?</b>	<b>N/A</b>
<b>Are all other tasks being performed safely?</b>	<b>Satisfactory</b>
<b>Any other items?</b>	<b>N/A</b>