

## **PROJECT INSPECTION**

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Mark Wilson Construction, Inc	Type of Inspection:	General Construction
Project	CCMC - Wound Care	Date of Inspection	December 27, 2024
Inspector Name	Jason Clark	Time of Inspection	04:18 PM

NOTES						
19	8	<b>0</b>	<b>11</b>			
Items Inspected	Satisfactory	Unsatisfactory	N/A			

1) Karsyn - begin taping and mud in various locations.

- 3) Nelson Continue painting first coat throughout
- 2) Fresno Plumbing Install new piping for gas to new roof units.

## **INSPECTION ITEMS**

General	
Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?	Satisfactory
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	Satisfactory
Is drinking water and shade set up sufficient for the amount of workers?	Satisfactory
Are emergency and labor law postings in place?	Satisfactory
Is Personal Protective Equipment being worn as required?	Satisfactory
	N1/A
Are scaffolding safety procedures being followed?	N/A
Are hand and power tools being used safely?	Satisfactory

Is good housekeeping being maintained?	Satisfactory
Is fall protection in place where required?	N/A
Is trenching & excavation work being done safely?	N/A
Are confined space safety procedures being followed?	N/A
Are scissor lifts / elevated platforms being used safely?	N/A
Are boom lifts and other aerial devices being used safely?	N/A
Is heavy equipment being used safely?	N/A
Are electrical items being used safely?	N/A
Are roofing operations being performed safely?	N/A
Is demolition work being done safely?	N/A
Are all other tasks being performed safely?	Satisfactory
Any other items?	N/A