

SAFETY INSPECTION REPORT

CONDUCTED FOR:
Mark Wilson Construction, Inc.

PROJECT:
Central Unified AG Building



INSPECTION TYPE:
General Construction

INSPECTOR : KIM BURGESS
DATE : OCTOBER 30, 2024
CITY : FRESNO
STATE : CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53 Items Inspected	31 Satisfactory	0 Unsatisfactory	22 N/A
------------------------------	---------------------------	----------------------------	------------------

Vince on site.

Reviewed all items in trailer.

Labor law postings present.

Emergency maps also visible.

First aid kit on site.

Fire extinguishers present.

First aid /CPR current.

TOD on site. PPE in compliance.

Holes in ground were covered.

Discussed future safety concerns. Metal building will be outsourced.

INSPECTION ITEMS

Documentation

Site Contact	Satisfactory
---------------------	---------------------

Safety Program (Including IIPP)	Satisfactory
--	---------------------

Comment	
---------	--

Safety Program is available	-
-----------------------------	---

Heat Illness Prevention Program	Satisfactory
--	---------------------

Comment	
---------	--

Heat Illness Prevention Program is available and site specific information is completed.	-
--	---

Safety Data Sheets	Satisfactory
---------------------------	---------------------

Comment	
---------	--

<p>TOD provided SDS sheets for materials on site</p>	
--	---

<p>Daily Inspections</p>	<p>Satisfactory</p>
---------------------------------	----------------------------

<p>Tailgate Meetings</p>	<p>Satisfactory</p>
---------------------------------	----------------------------

<p>Sub-Contractor Meetings</p>	<p>Satisfactory</p>
---------------------------------------	----------------------------

<p>OSHA Permits</p>	<p>Satisfactory</p>
----------------------------	----------------------------

<p>Labor Law Postings</p>	<p>Satisfactory</p>
----------------------------------	----------------------------

<p>Comment</p>	
<p>Labor law postings are in place as required.</p>	<p>-</p>

<p>Emergency / Other Postings</p>	<p>Satisfactory</p>
--	----------------------------

<p>Comment</p>	
<p>Emergency postings visible in trailer.</p>	

<p>First Aid / CPR Certification</p>	<p>Satisfactory</p>
---	----------------------------

<p>Comment</p>	
<p>Confirmed first aid /CPR current.</p>	<p>-</p>

Emergency Items

Access / Egress	Satisfactory
------------------------	---------------------

Elevator for Hoisting Workers (if needed)	N/A
--	------------

Fire Extinguisher(s)	Satisfactory
-----------------------------	---------------------

Comment

ABC fire extinguisher inspected once a month and once a year by a company	-
---	---

First Aid Kit(s)	Satisfactory
-------------------------	---------------------

Eye Wash Station	Satisfactory
-------------------------	---------------------

Other Fire Fighting Equipment (If needed)	N/A
--	------------

General Items

Restrooms	Satisfactory
------------------	---------------------

Comment

Plenty of toilets are located on site and are being kept clean and in good working order.	-
---	---

Hand Washing Stations	Satisfactory
------------------------------	---------------------

Comment

Wash stations are clean and in sanitary condition. There is an adequate supply of soap and paper towels.	-
--	---

Waste Containers	Satisfactory
-------------------------	---------------------

Potable Water	Satisfactory
----------------------	---------------------

Shade	Satisfactory
--------------	---------------------

Tools & Equipment


Power Tools	Satisfactory
Hand Tools	Satisfactory
Powder Actuated Tools	N/A
Pneumatic Nailers	N/A
Mobile Elevated Work Platforms (MEWP's)	N/A
Powered Industrial Trucks	Satisfactory
Heavy Mobile Equipment (Excavators, Loaders, etc)	Satisfactory
Cranes	N/A
Cylinder Storage	N/A
Ladders	Satisfactory

Operations

Personal Protective Equipment	Satisfactory
Comment	
All PPE being worn	-

Trenching & Excavation

Comment	
Open holes were Covered.	

Fall Protection	N/A
Guardrails	N/A
Floor / Wall Openings	N/A
Supported Scaffolding	N/A
Comment	
No scaffolding on site.	-
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Comment	
Protective covers designed to cover exposed reinforced steel and other similar projections so as to prevent impalement	
Traffic Control	N/A
Roofing Operations	N/A
Housekeeping	Satisfactory
Demolition	N/A

Silica Control	Satisfactory
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	Satisfactory
Lockout / Tagout	N/A
Stairways, Ramps, Runways	N/A
Other Items (that were observed)	N/A