

# **PROJECT INSPECTION**

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Mark Wilson Construction, Inc	Type of Inspection:	General Construction	n	
Project	Clovis DO Expansion	Date of Inspection	May 14, 2024		
Inspector Name	Jon Turl	Time of Inspection	04:42 PM		
NOTES					
lte	19 ems Inspected Sati	13 sfactory	0 Insatisfactory	<b>6</b> N/A	
INSPECTION ITEMS					
General					
Is emergency	Satisfactory				
Is safety docu	Satisfactory				
Is drinking wa	Satisfactory				
Crews had ad					
Crews had adequate drinking water -					
Are emergene	Satisfactory				
Is Personal P	Satisfactory				

Comment	
Type your custom comment	
Are scaffolding safety procedures being followed?	N/A
Are hand and power tools being used safely?	Satisfactory
ls good housekeeping being maintained?	Satisfactory
Is fall protection in place where required?	Satisfactory
ls trenching & excavation work being done safely?	Satisfactory
Comment	
Wild elect trenches	
Are confined space safety procedures being followed?	N/A

**Satisfactory** 

Are scissor lifts / elevated platforms being used safely?

#### Comment

Core framing using lifts safely



## Are boom lifts and other aerial devices being used safely?

N/A

### Is heavy equipment being used safely?

Satisfactory

#### Comment

Crawford using heavy earthwork equipment safely



### Are electrical items being used safely?

**Satisfactory** 

Are roofing operations being performed safely?

N/A

Is demolition work being done safely?

N/A

Are all other tasks being performed safely?

**Satisfactory** 

Any other items?

N/A