



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Mark Wilson Construction, Inc	Type of Inspection:	General Construction
Project	Clovis DO Expansion	Date of Inspection	August 09, 2024
Inspector Name	Jeremy Nagy	Time of Inspection	02:48 PM

NOTES


19 Items Inspected	14 Satisfactory	1 Unsatisfactory	4 N/A
-----------------------	--------------------	---------------------	----------

Sunny with high temperature of 106
AQI = Moderate mid 50's

High Heat Safety Meeting took place with each foreman onsite

Project activities consisting of framing, MEP rough in, fire sprinkler piping, single ply roofing, steel canopy/welding, column baseplate grouting, storefront window frames

INSPECTION ITEMS


General	
Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?	Satisfactory
Comment	
Fire extinguishers in place periodically throughout buildings	

Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)

Satisfactory

Comment

High Heat Safety Meeting took place in morning



Is drinking water and shade set up sufficient for the amount of workers?

Satisfactory

Comment

Type your custom comment...



Are emergency and labor law postings in place?

Satisfactory

Comment

Posted in job trailer




Is Personal Protective Equipment being worn as required?

Satisfactory

Comment

Type your custom comment...



Are scaffolding safety procedures being followed?


Satisfactory

Are hand and power tools being used safely?

Satisfactory

Comment

Cutting metal studs with proper face shield and back board in place



Is good housekeeping being maintained?

Satisfactory

Is fall protection in place where required?

Satisfactory

Comment

Type your custom comment...



Is trenching & excavation work being done safely?

N/A

Are confined space safety procedures being followed?


N/A

Are scissor lifts / elevated platforms being used safely?

Satisfactory

Comment

Type your custom comment...




Are boom lifts and other aerial devices being used safely?

Unsatisfactory

Comment

Fabtech worker/welder was caught in lift without having lanyard in place by safety compliance inspector. She noted correction in field.



Worker in boom lift basket not tied off



Is heavy equipment being used safely?

Satisfactory

Are electrical items being used safely?

Satisfactory

Comment

Type your custom comment...



Are roofing operations being performed safely?

Satisfactory

Comment

All openings covered



Is demolition work being done safely?

N/A

Are all other tasks being performed safely?

Satisfactory

Any other items?

N/A