

Inspector Name

Jeremy Nagy

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Time of

Inspection

03:15 PM

Company Mark Wilson Construction, Inc Type of Inspection: General Construction

Project Clovis DO Expansion Date of Inspection August 14, 2024

NOTES

19
Items Inspected

12
Satisfactory

1 06
N/A

8/14/24

Weather: sunny Temp high: 98

AQI = 47

Activities: Wood/metal framing, MEP rough in, fire sprinkler overhead piping, ceiling

insulation, irrigation, structural steel erection/welding

INSPECTION ITEMS

General

Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?

Satisfactory

Comment

Fire extinguishers throughout bldg and at cut stations



Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)

Satisfactory

Comment

Contractors SDS/IIPP's in project trailer



Is drinking water and shade set up sufficient for the amount of workers?

Satisfactory

Are emergency and labor law postings in place?

Satisfactory

Comment

Type your custom comment...



Is Personal Protective Equipment being worn as required?

Satisfactory

Comment

Type your custom comment...



Are scaffolding safety procedures being followed?

N/A

Are hand and power tools being used safely?

Satisfactory

Comment

Type your custom comment...



Is good housekeeping being maintained?

Satisfactory

Is fall protection in place where required?

N/A

Is trenching & excavation work being done safely?

Satisfactory

Are confined space safety procedures being followed?

N/A

Are scissor lifts / elevated platforms being used safely?

Unsatisfactory

Comment

Todd Plumbing employee in scissor lift without safety guard chain in place



Are boom lifts and other aerial devices being used safely?

Satisfactory

Comment

Type your custom comment...



Is heavy equipment being used safely?	Satisfactory
Are electrical items being used safely?	Satisfactory
Are roofing operations being performed safely?	N/A
Is demolition work being done safely?	N/A
Are all other tasks being performed safely?	Satisfactory
Comment	
Extension ladder tied off properly	

Any other items?