

General

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Inspection

Company Mark Wilson Construction, Inc Type of Inspection: General Construction

Project Clovis DO Expansion Date of Inspection October 04, 2024

Inspector Name Jeremy Nagy Time of Inspection 02:04 PM

NOTES

19

Items Inspected

14 Satisfactory **0** Unsatisfactory **5** N/A

INSPECTION ITEMS

Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)? Satisfactory

Comment

Fire extinguishers and evacuation plans posted



First aid kit in job box



Comment Available in job trailer	
Available in job trailer	
	-
s drinking water and shade set up sufficient for the amount of work	kers? Satisfactory
Comment	
	INSIDE
Shade canopy set up by roofers	
Are emergency and labor law postings in place?	Satisfactory
Comment	
s Personal Protective Equipment being worn as required?	Satisfactory
Comment	
Are scaffolding safety procedures being followed?	Satisfactory
Comment	
Are hand and power tools being used safely?	Satisfactory

N/A

Is fall protection in place where required?

Comment	
Scaffolding being used safely, roof has tall parapet walls. No fall hazard present	-
s trenching & excavation work being done safely?	Satisfactory
Comment	
Benching method used for deep trench	
Are confined space safety procedures being followed?	N/A
Are scissor lifts / elevated platforms being used safely?	Satisfactory
Comment	
Are boom lifts and other aerial devices being used safely?	N/A
s heavy equipment being used safely?	Satisfactory
Comment	
Are electrical items being used safely?	Satisfactory
Are roofing operations being performed safely?	Satisfactory
Comment	
s demolition work being done safely?	N/A
Are all other tasks being performed safely?	Satisfactory
Comment	

Form stakes are all capped



Any other items?