



# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Mark Wilson Construction, Inc	<b>Type of Inspection:</b>	General Construction
<b>Project</b>	Clovis DO Expansion	<b>Date of Inspection</b>	January 16, 2025
<b>Inspector Name</b>	Jeremy Nagy	<b>Time of Inspection</b>	11:22 AM

## NOTES

<b>19</b> Items Inspected	<b>13</b> Satisfactory	<b>0</b> Unsatisfactory	<b>6</b> N/A
------------------------------	---------------------------	----------------------------	-----------------

## INSPECTION ITEMS

### General

Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?

Satisfactory

Comment

Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)

Satisfactory

Comment

Is drinking water and shade set up sufficient for the amount of workers?

Satisfactory

Comment

Are emergency and labor law postings in place?

Satisfactory

Comment

Is Personal Protective Equipment being worn as required?

Satisfactory

Comment

Are scaffolding safety procedures being followed?

N/A

Are hand and power tools being used safely?	Satisfactory
Is good housekeeping being maintained?	Satisfactory
Is fall protection in place where required?	Satisfactory
Is trenching & excavation work being done safely?	Satisfactory
Comment	
Are confined space safety procedures being followed?	N/A
Are scissor lifts / elevated platforms being used safely?	Satisfactory
Comment	
Are boom lifts and other aerial devices being used safely?	N/A
Is heavy equipment being used safely?	Satisfactory
Are electrical items being used safely?	Satisfactory
Are roofing operations being performed safely?	N/A
Is demolition work being done safely?	N/A
Are all other tasks being performed safely?	Satisfactory
Any other items?	N/A