

SAFETY INSPECTION REPORT

CONDUCTED FOR:
Mark Wilson Construction, Inc.

PROJECT:
Clovis USD District Office Expansion



INSPECTION TYPE:
General Construction

INSPECTOR : ESPITIA GUS
DATE : DECEMBER 23, 2024
CITY : CLOVIS
STATE : CA.

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

54 Items Inspected	30 Satisfactory	0 Unsatisfactory	24 N/A
------------------------------	---------------------------	----------------------------	------------------

I met with Cody in the construction trailer, where the federal and state postings are properly displayed. The IIPP and safety program are also available in the trailer. A first aid kit and fire extinguishers are readily accessible on-site. Daily safety inspections and weekly tailgate meetings are being conducted as required.

Rodrigo and I walked the job site and observed that all workers were wearing the required PPE. The scaffolding structure had a green tag and was inspected today. Drinking water was readily available throughout the construction site. I did not observe any violations during the inspection. Overall, the site had good housekeeping and clean restrooms.

INSPECTION ITEMS

Documentation

Site Contact	Satisfactory
Comment	
Rodrigo and I walked the job site together.	-

Safety Program (Including IIPP)	Satisfactory
Comment	
Safety Program is available	-

Heat Illness Prevention Program	Satisfactory
Comment	
Heat Illness Prevention Program is available and site specific information is completed.	-


Safety Data Sheets	Satisfactory
Comment	
SDS are available for employee access	-


Daily Inspections		Satisfactory
Comment		
Daily inspections are being conducted		-

Tailgate Meetings		Satisfactory
Comment		
Tailgate meetings are being conducted		-

Sub-Contractor Meetings		N/A
--------------------------------	--	------------

OSHA Permits		Satisfactory
Comment		
Required Cal/OSHA permits have been pulled and are posted		-

Labor Law Postings		Satisfactory
Comment		
Labor law postings are in place as required.		

Emergency / Other Postings		Satisfactory
Comment		
Emergency posters are on site and directions to nearest medical facility are posted.		


First Aid / CPR Certification	Satisfactory
Comment	
Rodrigo and Cody are both first aid and CPR certified.	-

Emergency Items

Access / Egress	Satisfactory
------------------------	---------------------

Elevator for Hoisting Workers (if needed)	N/A
--	------------

Fire Extinguisher(s)	Satisfactory
Comment	
Fire extinguishers are readily available on-site	-

First Aid Kit(s)	Satisfactory
Comment	
A first aid kit is readily available on-site	

Eye Wash Station	Satisfactory
-------------------------	---------------------

Personnel Hoist	N/A
------------------------	------------

Other Fire Fighting Equipment (If needed)	N/A
--	------------

General Items

Restrooms	Satisfactory
Comment	

Plenty of toilets are located on site and are being kept clean and in good working order.	-
---	---

Hand Washing Stations	Satisfactory
------------------------------	---------------------

Comment	
----------------	--

Wash stations are clean and in sanitary condition. There is an adequate supply of soap and paper towels.	-
--	---

Waste Containers	Satisfactory
-------------------------	---------------------

Comment	
----------------	--

Waste containers provided	-
---------------------------	---

Potable Water	Satisfactory
----------------------	---------------------

Comment	
----------------	--

Drinking is available throughout the construction site	-
--	---

Shade	Satisfactory
--------------	---------------------

Comment	
----------------	--

Structural shade is available on-site	-
---------------------------------------	---

Tools & Equipment	
------------------------------	--

Power Tools	Satisfactory
--------------------	---------------------

Comment	
----------------	--

All power tools and equipment in good functional order	-
--	---

Hand Tools	Satisfactory
-------------------	---------------------

Powder Actuated Tools	N/A
------------------------------	------------

Pneumatic Nailers	N/A
--------------------------	------------

Mobile Elevated Work Platforms (MEWP's)	Satisfactory
--	---------------------

Comment	
----------------	--

The scissor lift operators are certified	-
--	---

Powered Industrial Trucks	N/A
----------------------------------	------------

Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
--	------------

Comment	
Heavy equipment was present but it was not in use during the inspection	-

Cranes	N/A
---------------	------------

Cylinder Storage	N/A
-------------------------	------------

Ladders	Satisfactory
----------------	---------------------

Comment	
Ladders were found to be in good condition and are being inspected daily	-

Operations

Personal Protective Equipment	Satisfactory
--------------------------------------	---------------------

Comment	
All PPE being worn	-

Trenching & Excavation	N/A
-----------------------------------	------------

Comment	
No open trenches on site	-

Fall Protection	N/A
------------------------	------------

Comment	
Nobody was working above the trigger that required the use of fall protection.	-

Guardrails	Satisfactory
-------------------	---------------------

Floor / Wall Openings	N/A
------------------------------	------------

Supported Scaffolding	Satisfactory
------------------------------	---------------------

Comment

The scaffolding structure is properly erected and was inspected today.



Mobile Scaffolding

Satisfactory

Suspended Scaffolding

N/A

Confined Spaces

N/A

Impalement Hazards

Satisfactory

Comment

Protective covers designed to cover exposed reinforced steel and other similar projections so as to prevent impalement

-

Traffic Control

N/A

Roofing Operations

N/A

Comment

No roofing operation during the inspection

-

Housekeeping

Satisfactory

Comment

Good housekeeping throughout the construction site

-

Demolition

N/A

Silica Control

N/A

Rigging Operations

N/A

Hot Work	N/A
-----------------	------------

Electrical Safety	Satisfactory
--------------------------	---------------------

Comment	
----------------	--

All extension cords are in good condition	-
---	---

Lockout / Tagout	N/A
-------------------------	------------

Stairways, Ramps, Runways	N/A
----------------------------------	------------

Other Items (that were observed)	N/A
---	------------