

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**  
Mark Wilson Construction, Inc.

**PROJECT:**  
Clovis USD Door Locks Project



**INSPECTION TYPE:**  
General Construction

**INSPECTOR:** KIM BURGESS  
**DATE:** JANUARY 30, 2025  
**CITY:** CLOVIS  
**STATE:** CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# SUMMARY OF INSPECTION

<b>53</b> Items Inspected	<b>26</b> Satisfactory	<b>0</b> Unsatisfactory	<b>27</b> N/A
------------------------------	---------------------------	----------------------------	------------------

EKC AND INFINITY ON SITE.

Met Brady on site.

Confirmed IIPP program on site.

Confirmed first aid kit on site.

Verified daily inspections completed on I Pad.

EKC and Infinity on site.

PPE in compliance.

Housekeeping in compliance.

Material storage good.

All efforts made to keep children at school away from work areas. Brady very active on site to help with this.

Brady completing CPR certification tomorrow.

# INSPECTION ITEMS

## Documentation

**Site Contact** **Satisfactory**

**Comment**

Brady present on site.


-

## Safety Program (Including IIPP)

**Satisfactory**

**Comment**

Mark Wilson

<p>Safety Program is available</p>	
------------------------------------	---

<p><b>Heat Illness Prevention Program</b> <span style="float: right;"><b>Satisfactory</b></span></p>	
<p style="text-align: center;"><b>Comment</b></p>	<p style="text-align: center;"><b>Mark Wilson</b></p>
<p>Verified heat illness programs in book.</p>	<p style="text-align: center;">-</p>

<p><b>Safety Data Sheets</b> <span style="float: right;"><b>Satisfactory</b></span></p>	
---	--

<p><b>Daily Inspections</b> <span style="float: right;"><b>Satisfactory</b></span></p>	
<p style="text-align: center;"><b>Comment</b></p>	<p style="text-align: center;"><b>Mark Wilson</b></p>
<p>Confirmed dailies completed on his I Pad</p>	<p style="text-align: center;">-</p>

<p><b>Tailgate Meetings</b> <span style="float: right;"><b>Satisfactory</b></span></p>	
<p style="text-align: center;"><b>Comment</b></p>	<p style="text-align: center;"><b>Mark Wilson</b></p>
<p>Tailgates are being conducted at least every 10 working days</p>	<p style="text-align: center;">-</p>

<p><b>Sub-Contractor Meetings</b> <span style="float: right;"><b>N/A</b></span></p>	
---	--

<p><b>OSHA Permits</b> <span style="float: right;"><b>Satisfactory</b></span></p>	
---	--

<p><b>Labor Law Postings</b> <span style="float: right;"><b>Satisfactory</b></span></p>	
---	--

<p><b>Emergency / Other Postings</b> <span style="float: right;"><b>Satisfactory</b></span></p>	
<p style="text-align: center;"><b>Comment</b></p>	<p style="text-align: center;"><b>Mark Wilson</b></p>

Emergency procedures implemented on site



**First Aid / CPR Certification**

**Satisfactory**

**Comment**

**Mark Wilson**

CPR training tomorrow Jan 31

-

**Emergency Items**

**Access / Egress**

**Satisfactory**

**Elevator for Hoisting Workers (if needed)**

**N/A**

**Fire Extinguisher(s)**

**Satisfactory**

**First Aid Kit(s)**

**Satisfactory**

**Comment**

**Mark Wilson**

First aid kit on site



**Eye Wash Station**

**N/A**

**Other Fire Fighting Equipment (If needed)**

**N/A**

## General Items

<b>Restrooms</b>	<b>Satisfactory</b>
------------------	---------------------

<b>Hand Washing Stations</b>	<b>Satisfactory</b>
------------------------------	---------------------

<b>Waste Containers</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Potable Water</b>	<b>Satisfactory</b>
----------------------	---------------------

Comment	Mark Wilson
Water supply adequate	-

<b>Shade</b>	<b>Satisfactory</b>
--------------	---------------------

## Tools & Equipment

<b>Power Tools</b>	<b>Satisfactory</b>
--------------------	---------------------

Comment	Mark Wilson
All power tools and equipment in good functional order	-

<b>Hand Tools</b>	<b>Satisfactory</b>
-------------------	---------------------

Comment	Mark Wilson
Powers tools are UL approved	-



<b>Powder Actuated Tools</b>	<b>N/A</b>
------------------------------	------------

Comment	Mark Wilson
No powder actuated tools on site.	-

<b>Pneumatic Nailers</b>	<b>N/A</b>
--------------------------	------------

<b>Mobile Elevated Work Platforms (MEWP's)</b>	<b>N/A</b>
--	------------

<b>Comment</b>	
No lifts operations on site.	-

<b>Powered Industrial Trucks</b>	<b>N/A</b>
----------------------------------	------------

<b>Comment</b>	
No reach lifts or fork lifts on site.	-


<b>Heavy Mobile Equipment (Excavators, Loaders, etc)</b>	<b>N/A</b>
--	------------

<b>Comment</b>	
No heavy equipment on site.	-

<b>Cranes</b>	<b>N/A</b>
---------------	------------

<b>Cylinder Storage</b>	<b>N/A</b>
-------------------------	------------

<b>Ladders</b>	<b>Satisfactory</b>
----------------	---------------------

<b>Comment</b>	
Ladders were found to be in good condition and are being inspected daily	infinity 

## Operations

<b>Personal Protective Equipment</b>	<b>Satisfactory</b>
--------------------------------------	---------------------

<b>Comment</b>	<b>EKC</b>
----------------	------------

All PPE being worn



<b>Trenching &amp; Excavation</b>	<b>N/A</b>
-----------------------------------	------------

<b>Fall Protection</b>	<b>N/A</b>
------------------------	------------

<b>Guardrails</b>	<b>N/A</b>
-------------------	------------

<b>Comment</b>	
No guard rails required thru out sites.	-

<b>Floor / Wall Openings</b>	<b>N/A</b>
------------------------------	------------

<b>Comment</b>	
No openings present on site.	-

<b>Supported Scaffolding</b>	<b>N/A</b>
------------------------------	------------

<b>Comment</b>	
No scaffolding on site.	-

<b>Mobile Scaffolding</b>	<b>N/A</b>
---------------------------	------------

<b>Suspended Scaffolding</b>	<b>N/A</b>
------------------------------	------------

<b>Confined Spaces</b>	<b>N/A</b>
------------------------	------------

<b>Comment</b>	
No confined spaces on site.	-

<b>Impalement Hazards</b>	<b>N/A</b>
---------------------------	------------

<b>Comment</b>	
----------------	--

No exposure to impalement hazards.	-
------------------------------------	---

<b>Traffic Control</b>	<b>N/A</b>
------------------------	------------

<b>Roofing Operations</b>	<b>N/A</b>
---------------------------	------------

<b>Comment</b>	
No roof work	-

<b>Housekeeping</b>	<b>Satisfactory</b>
---------------------	---------------------

<b>Comment</b>	
Housekeeping in good shape.	-

<b>Demolition</b>	<b>N/A</b>
-------------------	------------

<b>Comment</b>	
No demo work operations.	-

<b>Silica Control</b>	<b>N/A</b>
-----------------------	------------

<b>Rigging Operations</b>	<b>N/A</b>
---------------------------	------------

<b>Hot Work</b>	<b>N/A</b>
-----------------	------------

<b>Electrical Safety</b>	<b>Satisfactory</b>
--------------------------	---------------------

<b>Comment</b>	
Electrical safety good.	infinity
	-

<b>Lockout / Tagout</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Stairways, Ramps, Runways</b>	<b>N/A</b>
----------------------------------	------------


<b>Comment</b>	
No stairways at work areas.	-

<b>Other Items (that were observed)</b>	<b>Satisfactory</b>
---	---------------------

<b>Comment</b>	
	Mark Wilson



Caution tape set where work is performed. Children present so Brady active on site to prevent any issues.



**Comment**

**Mark Wilson**

Another area where caution tape set when working around children

