

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Mark Wilson Construction, Inc	Type of Inspection:	General Construction
Project	CUSD DO Phase 2	Date of Inspection	January 16, 2025
Inspector Name	Jon Turl	Time of Inspection	08:56 AM

	NOTES		
19	9	0	10
Items Inspected	Satisfactory	Unsatisfactory	N/A

Ongoing clear and grub, yard prep construction continues safely

INSPECTION ITEMS

General	
Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?	Satisfactory
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	Satisfactory
Is drinking water and shade set up sufficient for the amount of workers?	Satisfactory
Are emergency and labor law postings in place?	Satisfactory
Is Personal Protective Equipment being worn as required?	Satisfactory
Are scaffolding safety procedures being followed?	N/A
Are hand and power tools being used safely?	N/A
Is good housekeeping being maintained?	Satisfactory

Is fall protection	in	place	where	required?
--------------------	----	-------	-------	-----------

Is trenching & excavation work being done safely?	Satisfactory
Comment	
Yard logistics	
Are confined space safety procedures being followed?	N/A
Are scissor lifts / elevated platforms being used safely?	N/A
Are boom lifts and other aerial devices being used safely?	N/A
s heavy equipment being used safely?	Satisfactory
Comment	

Todd equip i	n use safely
--------------	--------------

Are electrical items being used safely?	N/A
Are roofing operations being performed safely?	N/A
Is demolition work being done safely?	N/A
Are all other tasks being performed safely?	Satisfactory

N/A