

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Mark Wilson Construction, Inc	Type of Inspection:	General Construction	on		
Project	CUSD DO Phase 2	Date of Inspection	January 14, 2025			
Inspector Name	Jeremy Nagy	Time of Inspection	10:16 AM			
NOTES						
		MOIL3				
lte	19 ems Inspected	12 Satisfactory	1 Unsatisfactory	6 N/A		
INSPECTION ITEMS						
General						
Is emergency	Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)? Satisfactor					
	Comment					
Is safety doc Meetings)	Satisfactory					
	Comment					
Is drinking w	Satisfactory					
Are emergen	Satisfactory					
Is Personal P	Unsatisfactory					

Low voltage contractor EKC employee without hard hat. MWC stopped worker at work and made him go put on hard hat



Are scaffolding safety procedures being followed?	N/A
Are hand and power tools being used safely?	Satisfactory
Is good housekeeping being maintained?	Satisfactory
Is fall protection in place where required?	Satisfactory
Is trenching & excavation work being done safely?	Satisfactory
Are confined space safety procedures being followed?	N/A
Are scissor lifts / elevated platforms being used safely?	Satisfactory
Comment	
Are boom lifts and other aerial devices being used safely?	N/A
Is heavy equipment being used safely?	Satisfactory
Is heavy equipment being used safely? Comment	Satisfactory
• • • • • • • • • • • • • • • • • • • •	Satisfactory Satisfactory
Comment	•
Comment Are electrical items being used safely?	Satisfactory
Comment Are electrical items being used safely? Are roofing operations being performed safely?	Satisfactory N/A