

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Mark Wilson Construction, Inc	Type of Inspection:	General Construction
Project	CUSD DO Phase 2	Date of Inspection	January 15, 2025
Inspector Name	Jeremy Nagy	Time of Inspection	01:18 PM

NOTES						
19	13	0	6			
Items Inspected	Satisfactory	Unsatisfactory	N/A			

INSPECTION ITEMS

General	
Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?	Satisfactory
Comment	
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	Satisfactory
Comment	
Is drinking water and shade set up sufficient for the amount of workers?	Satisfactory
Are emergency and labor law postings in place?	Satisfactory
Comment	
Is Personal Protective Equipment being worn as required? Comment	Satisfactory
Are scaffolding safety procedures being followed?	N/A
Are hand and power tools being used safely?	Satisfactory

Is good housekeeping being maintained?	Satisfactory
Is fall protection in place where required?	Satisfactory
Is trenching & excavation work being done safely?	Satisfactory
Comment	
Are confined space safety procedures being followed?	N/A
Are scissor lifts / elevated platforms being used safely?	Satisfactory
Are boom lifts and other aerial devices being used safely?	N/A
Is heavy equipment being used safely?	Satisfactory
Are electrical items being used safely?	Satisfactory
Are roofing operations being performed safely?	N/A
Is demolition work being done safely?	N/A
Are all other tasks being performed safely?	Satisfactory
Any other items?	N/A