

## **PROJECT INSPECTION**

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Mark Wilson Construction, Inc	Type of Inspection:	General Construction
Project	CUSD DO Phase 2	Date of Inspection	January 21, 2025
Inspector Name	Jon Turl	Time of Inspection	08:19 AM

NOTES					
19	9	0	10		
Items Inspected	Satisfactory	Unsatisfactory	N/A		

19 Items Inspected	9 Satisfactory	<b>0</b> Unsatisfactory	<b>10</b> N/A			
INSPECTION ITEMS						
General						
Is emergency equipment available, includ	Satisfactory					
Is safety documentation available (Writter Meetings)	Satisfactory					
Is drinking water and shade set up suffici	Satisfactory					
Are emergency and labor law postings in	Satisfactory					
Is Personal Protective Equipment being w	Satisfactory					
Comment						
Todd EW						

Is Personal Protective Equipment being worn as required?	Satisfactory
Comment	
Todd EW	

Are scaffolding safety procedures being followed?	N/A
Are hand and power tools being used safely?	N/A
Is good housekeeping being maintained?	Satisfactory
Is fall protection in place where required?	N/A
Is trenching & excavation work being done safely?	Satisfactory
Are confined space safety procedures being followed?	N/A
Are scissor lifts / elevated platforms being used safely?	N/A
Are boom lifts and other aerial devices being used safely?	N/A
Is heavy equipment being used safely?	Satisfactory
Are electrical items being used safely?	N/A
Are roofing operations being performed safely?	N/A
Is demolition work being done safely?	N/A
Are all other tasks being performed safely?	Satisfactory
Any other items?	N/A