

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

| Company | Mark Wilson Construction, Inc | Type of Inspection: | General Construction |
|----------------|-------------------------------|------------------------|----------------------|
| Project | CUSD Locks Phase 3 | Date of Inspection | January 15, 2025 |
| Inspector Name | Brady Bolock | Time of Inspection | 07:23 AM |

| NOTES | | | | | |
|-----------------|--------------|----------------|----------|--|--|
| 19 | 10 | 0 | 9 | | |
| Items Inspected | Satisfactory | Unsatisfactory | N/A | | |

INSPECTION ITEMS

| General | |
|--|--------------|
| Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)? | Satisfactory |
| Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings) | Satisfactory |
| Is drinking water and shade set up sufficient for the amount of workers? | Satisfactory |
| Are emergency and labor law postings in place? | Satisfactory |
| Is Personal Protective Equipment being worn as required? | Satisfactory |
| Are scaffolding safety procedures being followed? | N/A |
| Are hand and power tools being used safely? | Satisfactory |
| Is good housekeeping being maintained? | Satisfactory |
| Is fall protection in place where required? | N/A |

| Is trenching & excavation work being done safely? | N/A |
|--|--------------|
| Are confined space safety procedures being followed? | N/A |
| Are scissor lifts / elevated platforms being used safely? | N/A |
| Are boom lifts and other aerial devices being used safely? | N/A |
| Is heavy equipment being used safely? | N/A |
| Are electrical items being used safely? | Satisfactory |
| Are roofing operations being performed safely? | N/A |
| Is demolition work being done safely? | N/A |
| Are all other tasks being performed safely? | Satisfactory |
| | |