

SAFETY INSPECTION REPORT

CONDUCTED FOR:
Mark Wilson Construction, Inc.

PROJECT:
Grace Church



INSPECTION TYPE:
General Construction

INSPECTOR : FRANCISCO ROMERO
DATE : AUGUST 06, 2024
CITY : KINGSBURG
STATE : CALIFORNIA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53 Items Inspected	35 Satisfactory	0 Unsatisfactory	18 N/A
------------------------------	---------------------------	----------------------------	------------------

At my arrival , I went to the site trailer and met the superintendent, we talked briefly and we did the walk together.

Subs on site today:

California Retail

During the inspection , we found no violations on site .

I will forward report for their review.

INSPECTION ITEMS

Documentation	
Site Contact	Satisfactory
Safety Program (Including IIPP)	Satisfactory
Heat Illness Prevention Program	Satisfactory
Safety Data Sheets	Satisfactory
Daily Inspections	Satisfactory
Tailgate Meetings	Satisfactory
Sub-Contractor Meetings	Satisfactory
OSHA Permits	Satisfactory
Labor Law Postings	Satisfactory

Emergency / Other Postings	Satisfactory
----------------------------	--------------

First Aid / CPR Certification	Satisfactory
-------------------------------	--------------

Emergency Items

Access / Egress	Satisfactory
-----------------	--------------

Elevator for Hoisting Workers (if needed)	N/A
---	-----

Fire Extinguisher(s)	Satisfactory
----------------------	--------------

First Aid Kit(s)	Satisfactory
------------------	--------------

Eye Wash Station	Satisfactory
------------------	--------------

Other Fire Fighting Equipment (If needed)	N/A
---	-----

General Items

Restrooms	Satisfactory
-----------	--------------

Hand Washing Stations	Satisfactory
-----------------------	--------------

Waste Containers	Satisfactory
------------------	--------------

Potable Water	Satisfactory
---------------	--------------

Shade	Satisfactory
-------	--------------

Tools & Equipment


Power Tools	Satisfactory
-------------	--------------

Hand Tools	Satisfactory
------------	--------------

Powder Actuated Tools	N/A
Pneumatic Nailers	N/A
Mobile Elevated Work Platforms (MEWP's)	Satisfactory
Powered Industrial Trucks	N/A
Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Cranes	N/A
Cylinder Storage	N/A
Ladders	Satisfactory

Operations

Personal Protective Equipment	Satisfactory
--------------------------------------	---------------------


Comment	
During the inspection , I found a couple of workers and they were both wearing proper PPE on site	

Trenching & Excavation	N/A
-----------------------------------	------------

Fall Protection	Satisfactory
------------------------	---------------------

Guardrails	Satisfactory
-------------------	---------------------

Floor / Wall Openings	Satisfactory
------------------------------	---------------------

Supported Scaffolding	N/A
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Comment	
During the inspection, I verified all metal stakes were capped properly	
Traffic Control	Satisfactory
Roofing Operations	Satisfactory
Housekeeping	Satisfactory
Demolition	N/A
Silica Control	Satisfactory
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	Satisfactory

Lockout / Tagout	Satisfactory
Stairways, Ramps, Runways	N/A
Other Items (that were observed)	N/A