### SAFETY INSPECTION REPORT

#### **CONDUCTED FOR:**

Mark Wilson Construction, Inc.

#### **PROJECT:**

Justin Garza Aquatic Complex/Soccer Field



# **INSPECTION TYPE:**General Construction

**INSPECTOR: KIM BURGESS** 

**DATE**: JUNE 11, 2024

CITY: FRESNO STATE: CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

**Satisfactory** 

# SUMMARY OF INSPECTION 53 Items Inspected Satisfactory O Unsatisfactory N/A

Matt on site. Valley Fence, Wild Electric, CCP and TODD on site. Due to high temps made sure all subs had adequate water and shade available to all workers. Matt completing daily inspections and tailgate meetings on safety app. All postings in trailer are current. PPE in compliance. Not a lot of activity on site as project is winding down.

## **INSPECTION ITEMS** Documentation **Site Contact** Satisfactory Comment Matt on site. Safety Program (Including IIPP) **Satisfactory Heat Illness Prevention Program** Satisfactory Comment High heat temps documented. All workers had required shade and water **Safety Data Sheets** Satisfactory **Daily Inspections Satisfactory**

**Tailgate Meetings** 

Sub-Contractor Meetings	Satisfactory
OSHA Permits	Satisfactory
Labor Law Postings	Satisfactory
Emergency / Other Postings	Satisfactory
First Aid / CPR Certification	Satisfactory
Emergency Items	
Access / Egress	Satisfactory
Elevator for Hoisting Workers (if needed)	N/A
Fire Extinguisher(s)	Satisfactory
First Aid Kit(s)	Satisfactory
Eye Wash Station	Satisfactory
Other Fire Fighting Equipment (If needed)	N/A
General Items	
Restrooms	Satisfactory
Hand Washing Stations	Satisfactory
Waste Contatiners	Satisfactory
Potable Water	Satisfactory
Comment	

Workers had access to cool potable water. In compliance with Cal OSHA water requirements.	-
Shade	Satisfactory
Tools & Equipment	
Power Tools	Satisfactory
Hand Tools	Satisfactory
Powder Actuated Tools	N/A
Pneumatic Nailers	N/A
Mobile Elevated Work Plarforms (MEWP's)	N/A
Powered Industrial Trucks	N/A
Heavy Mobile Equipment (Excavators, Loaders, etc)	Satisfactory
Comment	
TODD in compliance	
Cranes	N/A
Cylinder Storage	N/A
Ladders	Satisfactory

## Operations

Personal Protective Equipment	Satisfactory
Trenching & Excavation	Satisfactory
Fall Protection	N/A
Guardrails	N/A
Floor / Wall Openings	N/A
Supported Scaffolding	N/A
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Traffic Control	N/A
Roofing Operations	N/A
Housekeeping	Satisfactory
Demolition	N/A
Silica Control	Satisfactory
Rigging Operations	N/A
Hot Work	Satisfactory
Electrical Safety	Satisfactory

Lockout / Tagout	Satisfactory
Stairways, Ramps, Runways	N/A
Other Items (that were observed)	N/A