

## **PROJECT INSPECTION**

Gen	erated by Safety Compliance App ww	w.safetycompliance.	com   www.safetycom	plianceapp.com
Company	Mark Wilson Construction, Inc	Type of Inspection:	General Constructio	n
Project	Justin Garza Athletic Complex	Date of Inspection	May 29, 2024	
Inspector Name	Matt Dresselhaus	Time of Inspection	04:22 PM	
		NOTES		
19 11 1 Unsatisfactory			<b>7</b> N/A	
	INSPE	CTION ITE	MS	
General				
Is emergency	Satisfactory			
Is safety docu	Satisfactory			
Is drinking wa	Satisfactory			
Are emergene	Satisfactory			
Is Personal Protective Equipment being worn as required?				Unsatisfactory
	Comment			
Had to remino	I EB guys to wear hard hats		-	
Are scaffolding safety procedures being followed?				N/A
Are hand and power tools being used safely?				Satisfactory
Is good housekeeping being maintained?			Satisfactory	

Is fall protection in place where required?	N/A
Is trenching & excavation work being done safely?	N/A
Are confined space safety procedures being followed?	N/A
Are scissor lifts / elevated platforms being used safely?	N/A
Are boom lifts and other aerial devices being used safely?	Satisfactory
Is heavy equipment being used safely?	Satisfactory
Are electrical items being used safely?	Satisfactory
Are roofing operations being performed safely?	N/A
Is demolition work being done safely?	N/A
Are all other tasks being performed safely?	Satisfactory
Any other items?	Satisfactory