

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Gen	erated by Safety Compliance App (www.satetycompilance.c	om www.satetycom	ipiianceapp.com	
Company	Mark Wilson Construction, Inc	Type of Inspection:	General Construction	on	
Project	Justin Garza Athletic Phase 2	Date of Inspection	February 19, 2025		
Inspector Name	Matt Dresselhaus	Time of Inspection	04:04 PM		
NOTES					
lte	19 ems Inspected	13	1 Insatisfactory	5 N/A	
INSPECTION ITEMS					
General					
Is emergency	Satisfactory				
Is safety docu Meetings)	Satisfactory				
Is drinking water and shade set up sufficient for the amount of workers?				Satisfactory	
Are emergency and labor law postings in place?				Satisfactory	
Is Personal P	Unsatisfactory				
Comment					
Had to remind Chazmat guys to wear hardhats.					
Are scaffolding safety procedures being followed?				Satisfactory	
Are hand and power tools being used safely?				Satisfactory	
Is good housekeeping being maintained?				Satisfactory	

Is fall protection in place where required?	N/A
Is trenching & excavation work being done safely?	Satisfactory
Are confined space safety procedures being followed?	N/A
Are scissor lifts / elevated platforms being used safely?	N/A
Are boom lifts and other aerial devices being used safely?	Satisfactory
Is heavy equipment being used safely?	Satisfactory
Are electrical items being used safely?	Satisfactory
Are roofing operations being performed safely?	N/A
Is demolition work being done safely?	N/A
Are all other tasks being performed safely?	Satisfactory
Any other items?	Satisfactory