



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Mark Wilson Construction, Inc	Type of Inspection:	General Construction
Project	Justin Garza Athletic Phase 2	Date of Inspection	February 25, 2025
Inspector Name	Matt Dresselhaus	Time of Inspection	04:14 PM

NOTES

19 Items Inspected	14 Satisfactory	1 Unsatisfactory	4 N/A
-----------------------	--------------------	---------------------	----------

INSPECTION ITEMS

General

Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?	Satisfactory
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	Satisfactory
Is drinking water and shade set up sufficient for the amount of workers?	Satisfactory
Are emergency and labor law postings in place?	Satisfactory
Is Personal Protective Equipment being worn as required?	Satisfactory
Are scaffolding safety procedures being followed?	Unsatisfactory
Comment	
Directly below the ladder to the scaffold was a rack for holding scaffold parts that had vertical angle iron bars on it.	-
Are hand and power tools being used safely?	Satisfactory

Is good housekeeping being maintained?	Satisfactory
Is fall protection in place where required?	N/A
Is trenching & excavation work being done safely?	Satisfactory
Are confined space safety procedures being followed?	N/A
Are scissor lifts / elevated platforms being used safely?	Satisfactory
Are boom lifts and other aerial devices being used safely?	Satisfactory
Is heavy equipment being used safely?	Satisfactory
Are electrical items being used safely?	Satisfactory
Are roofing operations being performed safely?	N/A
Is demolition work being done safely?	N/A
Are all other tasks being performed safely?	Satisfactory
Any other items?	Satisfactory