

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**  
Mark Wilson Construction, Inc.

**PROJECT:**  
Sheehy Elementary



**INSPECTION TYPE:**  
General Construction

**INSPECTOR :** ESPITIA GUS  
**DATE :** JUNE 05, 2024  
**CITY :** MERCED  
**STATE :** CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# SUMMARY OF INSPECTION

<b>52</b> Items Inspected	<b>27</b> Satisfactory	<b>0</b> Unsatisfactory	<b>25</b> N/A
------------------------------	---------------------------	----------------------------	------------------

As I arrived at the job site, I met with Jeremy in the construction trailer. The regulatory posters were displayed, along with the company's emergency information. The first aid kit and fire extinguisher were readily available. As I walked the construction site, all activity was outside, with workers preparing for concrete pouring, trenching for sprinklers, and plastering. There was not much activity inside the building. The job site had good housekeeping.

## INSPECTION ITEMS

Documentation	
<b>Site Contact</b>	<b>Satisfactory</b>
<b>Comment</b>	
Met with Jermy on job site	-
<b>Safety Program (Including IIPP)</b>	<b>Satisfactory</b>
<b>Comment</b>	
The safety programs are on site and available	-
<b>Heat Illness Prevention Program</b>	<b>Satisfactory</b>
<b>Comment</b>	
Heat Illness Prevention Program is available and site specific information is completed.	-
<b>Safety Data Sheets</b>	<b>Satisfactory</b>
<b>Comment</b>	
SDS are available for employee access	-
<b>Daily Inspections</b>	<b>Satisfactory</b>
<b>Comment</b>	
Daily inspections are being performed	-

**Tailgate Meetings** **Satisfactory**

**Comment**

Weekly tailgating training are being conducted	-
--	---


**Sub-Contractor Meetings** **N/A**

**OSHA Permits** **Satisfactory**

**Labor Law Postings** **Satisfactory**

**Comment**


Federal and state posters are readily available on site



**Emergency / Other Postings** **Satisfactory**

**Comment**

Map to emergency clinic is posted



**First Aid / CPR Certification** **Satisfactory**

**Emergency Items**

**Access / Egress** **Satisfactory**

**Fire Extinguisher(s)** **Satisfactory**

<b>First Aid Kit(s)</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Comment</b>	
----------------	--

First aid kit is readily available and fully replenished



<b>Eye Wash Station</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Other Fire Fighting Equipment (If needed)</b>	<b>N/A</b>
--	------------

<b>General Items</b>	
----------------------	--

<b>Restrooms</b>	<b>Satisfactory</b>
------------------	---------------------

<b>Comment</b>	
----------------	--

Cleaned restroom on site.

-


<b>Hand Washing Stations</b>	<b>Satisfactory</b>
------------------------------	---------------------

<b>Waste Containers</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Potable Water</b>	<b>Satisfactory</b>
----------------------	---------------------

<b>Comment</b>	
----------------	--

Bottle water is readily available on site



<b>Shade</b>	<b>Satisfactory</b>
<b>Comment</b>	
Structure shade is available	-

## Tools & Equipment

<b>Power Tools</b>	<b>Satisfactory</b>
--------------------	---------------------

<b>Hand Tools</b>	<b>Satisfactory</b>
-------------------	---------------------

<b>Powder Actuated Tools</b>	<b>N/A</b>
------------------------------	------------

<b>Pneumatic Nailers</b>	<b>N/A</b>
--------------------------	------------

<b>Mobile Elevated Work Platforms (MEWP's)</b>	<b>N/A</b>
--	------------

<b>Powered Industrial Trucks</b>	<b>N/A</b>
----------------------------------	------------

<b>Heavy Mobile Equipment (Excavators, Loaders, etc)</b>	<b>N/A</b>
--	------------

<b>Cranes</b>	<b>N/A</b>
---------------	------------

<b>Cylinder Storage</b>	<b>N/A</b>
-------------------------	------------

<b>Ladders</b>	<b>Satisfactory</b>
----------------	---------------------

## Operations

<b>Personal Protective Equipment</b>	<b>Satisfactory</b>
--------------------------------------	---------------------

<b>Comment</b>	
All worker were wearing the required PPE	-

<b>Trenching &amp; Excavation</b>	<b>Satisfactory</b>
-----------------------------------	---------------------

<b>Comment</b>	
Sprinkler trench in 16 inches deep	-

<b>Fall Protection</b>	<b>N/A</b>
------------------------	------------

<b>Comment</b>	
----------------	--

No one working on heights	-
---------------------------	---

<b>Guardrails</b>	<b>N/A</b>
-------------------	------------

<b>Floor / Wall Openings</b>	<b>N/A</b>
------------------------------	------------

<b>Supported Scaffolding</b>	<b>N/A</b>
------------------------------	------------

<b>Mobile Scaffolding</b>	<b>N/A</b>
---------------------------	------------

<b>Suspended Scaffolding</b>	<b>N/A</b>
------------------------------	------------

<b>Confined Spaces</b>	<b>N/A</b>
------------------------	------------

<b>Impalement Hazards</b>	<b>Satisfactory</b>
---------------------------	---------------------

<b>Comment</b>	
----------------	--

All stakes on site had the safety caps on
---



<b>Traffic Control</b>	<b>N/A</b>
------------------------	------------

<b>Roofing Operations</b>	<b>N/A</b>
---------------------------	------------

<b>Comment</b>	
----------------	--

No roofing operation on site	-
------------------------------	---

<b>Housekeeping</b>	<b>Satisfactory</b>
---------------------	---------------------

<b>Comment</b>	
----------------	--

Good housekeeping on site	-
<b>Demolition</b>	<b>N/A</b>
<b>Silica Control</b>	<b>N/A</b>
<b>Rigging Operations</b>	<b>N/A</b>
<b>Hot Work</b>	<b>N/A</b>
<b>Electrical Safety</b>	<b>Satisfactory</b>
<b>Lockout / Tagout</b>	<b>N/A</b>
<b>Stairways, Ramps, Runways</b>	<b>N/A</b>
<b>Other Items (that were observed)</b>	<b>N/A</b>