



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

| | | | |
|-----------------------|-------------------------------|----------------------------|----------------------|
| Company | Mark Wilson Construction, Inc | Type of Inspection: | General Construction |
| Project | Stone Creek | Date of Inspection | December 17, 2024 |
| Inspector Name | Jeff Copeland | Time of Inspection | 12:57 PM |

NOTES

| | | | |
|------------------------------|--------------------------|----------------------------|------------------|
| 19 Items Inspected | 4 Satisfactory | 0 Unsatisfactory | 15 N/A |
|------------------------------|--------------------------|----------------------------|------------------|

INSPECTION ITEMS

General

Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)? **Satisfactory**

Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings) **Satisfactory**

Is drinking water and shade set up sufficient for the amount of workers? **Satisfactory**

Are emergency and labor law postings in place? **Satisfactory**

Is Personal Protective Equipment being worn as required? **N/A**

Are scaffolding safety procedures being followed? **N/A**

Are hand and power tools being used safely? **N/A**

Is good housekeeping being maintained? **N/A**

Is fall protection in place where required? **N/A**

| | |
|---|------------|
| Is trenching & excavation work being done safely? | N/A |
| Are confined space safety procedures being followed? | N/A |
| Are scissor lifts / elevated platforms being used safely? | N/A |
| Are boom lifts and other aerial devices being used safely? | N/A |
| Is heavy equipment being used safely? | N/A |
| Are electrical items being used safely? | N/A |
| Are roofing operations being performed safely? | N/A |
| Is demolition work being done safely? | N/A |
| Are all other tasks being performed safely? | N/A |
| Any other items? | N/A |