

SAFETY INSPECTION REPORT

CONDUCTED FOR:
Mark Wilson Construction, Inc.

PROJECT:
Stonecreek Elementary classroom



INSPECTION TYPE:
General Construction

INSPECTOR : KIM BURGESS
DATE : NOVEMBER 25, 2024
CITY : MADERA
STATE : CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53 Items Inspected	23 Satisfactory	0 Unsatisfactory	30 N/A
------------------------------	---------------------------	----------------------------	------------------


Jeff and Jose in the trailer.
 Confirmed postings were present
 Safety data sheets were printed for paint.
 Emergency evacuation map set.
 Restrooms were serviced on Nov 20th. Confirmed water, soap and paper towels present.

INSPECTION ITEMS


Documentation	
Site Contact	Satisfactory
Safety Program (Including IIPP)	Satisfactory
Comment	
Safety Program is available	-
Heat Illness Prevention Program	Satisfactory
Comment	
Heat illness plan located in safety book. Both outdoor and indoor.	-
Safety Data Sheets	Satisfactory
Comment	
Safety data sheets were printed for paint in the trailer.	-
Daily Inspections	Satisfactory
Tailgate Meetings	Satisfactory
Sub-Contractor Meetings	N/A

OSHA Permits	Satisfactory
---------------------	---------------------

Labor Law Postings	Satisfactory
---------------------------	---------------------

Comment	
Labor law postings are in place as required.	

Emergency / Other Postings	Satisfactory
-----------------------------------	---------------------

Comment	
Emergency evacuation map Posted.	

First Aid / CPR Certification	Satisfactory
--------------------------------------	---------------------

Comment	
First aid /CPR certification current.	-

Emergency Items

Access / Egress	Satisfactory
------------------------	---------------------

Elevator for Hoisting Workers (if needed)	N/A
--	------------

Fire Extinguisher(s)	Satisfactory
-----------------------------	---------------------

First Aid Kit(s)	Satisfactory
-------------------------	---------------------

Comment	
----------------	--

First aid kit located in the job trailer.	
---	---

Eye Wash Station	N/A
-------------------------	------------

Other Fire Fighting Equipment (If needed)	N/A
--	------------

General Items	
----------------------	--

Restrooms	Satisfactory
------------------	---------------------

Comment	
----------------	--

Plenty of toilets are located on site and are being kept clean and in good working order.	-
---	---

Hand Washing Stations	Satisfactory
------------------------------	---------------------

Comment	
----------------	--

Wash stations are clean and in sanitary condition. There is an adequate supply of soap and paper towels.	-
--	---

Waste Containers	Satisfactory
-------------------------	---------------------


Potable Water	Satisfactory
----------------------	---------------------

Shade	Satisfactory
--------------	---------------------

Tools & Equipment	
------------------------------	--

Power Tools	N/A
--------------------	------------

Hand Tools	N/A
Powder Actuated Tools	N/A
Pneumatic Nailers	N/A
Mobile Elevated Work Platforms (MEWP's)	N/A
Powered Industrial Trucks	N/A
Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Comment	
No equipment being operated on site.	-
Cranes	N/A
Cylinder Storage	N/A
Ladders	N/A
Operations	
Personal Protective Equipment	Satisfactory
Comment	
No subs on site. Hard hats and high visibility vests located in trailer for use.	-
Trenching & Excavation	N/A
Fall Protection	N/A
Guardrails	N/A
Floor / Wall Openings	N/A

Supported Scaffolding		N/A
Comment		
No scaffolding on site.		-
Mobile Scaffolding		N/A
Suspended Scaffolding		N/A
Confined Spaces		N/A
Impalement Hazards		Satisfactory
Comment		
No impalement hazards on site.		
Traffic Control		N/A
Roofing Operations		N/A
Housekeeping		Satisfactory
Demolition		N/A
Silica Control		N/A
Rigging Operations		N/A
Hot Work		N/A
Comment		

No hot work on site.	-
----------------------	---

Electrical Safety	Satisfactory
--------------------------	---------------------

Lockout / Tagout	N/A
-------------------------	------------

Stairways, Ramps, Runways	Satisfactory
----------------------------------	---------------------

Comment	
----------------	--

Stairs to job trailer in compliance.	-
--------------------------------------	---

Other Items (that were observed)	N/A
---	------------