

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

	erated by Safety Compliance App www.s	aretycomphanice.	com www.saretycom	прпапсеарр.соп	
Company	Marvulli INC	Type of Inspection:	Framing Inspection	ı	
Project	22-240 Hilton Garden Inn	Date of Inspection	July 12, 2024		
Inspector Name	Michael Tolhurst	Time of Inspection	02:03 PM		
NOTES					
lte	14	13	1 Unsatisfactory	0 N/A	
INSPECTION ITEMS					
General					
Are air compressors and generators set up safely?				Satisfactory	
Are nail guns being used safely?				Satisfactory	
Are hole and wall openings protected per OSHA regulations?				Unsatisfactory	
Comment					
HVAC opening	gs at low roof with no protection		-		
Are stairways in place as required?				Satisfactory	
If personal fall restraint / arrest systems are being used, are the anchors and lanyards set up correctly?				Satisfactory	
is emergency equipment, including first aid kits and fire extinguishers available?				Satisfactory	
Are emergend	cy and labor law postings in place?			Satisfactory	
Is scaffolding	set up correctly and being used saf	ely?		Satisfactory	

Is fall protection in place where required?	Satisfactory
Is all required PPE being worn including hard hats and eye protection?	Satisfactory
Are electrical cords and other electrical related items in safe condition?	Satisfactory
Are hand and power tools being used safely?	Satisfactory
Is the company safety manual on site?	Satisfactory
Are SDS on site and available to employees?	Satisfactory